

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 25 Jul 2023

Preliminary Advice

Insured Vehicle No	: FBH5679T	Accident Date	: 25/07/2022
TP Vehicle No	: FBT594Z	Assignment Date	: 27/10/2022
Make	: YAMAHA MT-03 ABS (MTN320-A)	Est. Duration of Repair	: 04
Date of Inspection	: 04/11/2022		
Inspection At	: WIN AUTOMOTIVE SERVICES		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,783.00
Revised Amount	:S\$	3,004.70
Check Items (Estimated)	:S\$	
Total	:S\$	3,004.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.