



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22010686/Eny3e2 Date: 21/03/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1995S	Veh. Inspected	SLM 3381U
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/10/22/2074	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	27/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703554455	Colour	WHITE
Odometer	302337 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R15	FIRESTONE	4 mm
L/H Front Tyre	195/50 R15	FIRESTONE	4 mm
R/H Rear Tyre	195/50 R15	FIRESTONE	4 mm
L/H Rear Tyre	195/50 R15	FIRESTONE	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/10/2022	Inspection Date	28/10/2022
Survey held at	No. 4 Jalan Besut S(619557)		
Repairer	LION CITY RENTALS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	