

Auto

Division of Vantage Automotive Limited)
Business Registration No. 53399829L GST Registration No. M2-0000551-1

BYD

305 Alexandra Road
159942 Singapore
Tel : 6376 8833
Fax : 6477 7398

GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. BY 5558	Date Estimated 27/10/2022	Page No. 1 of 2
	Prepared By Clement Chia Cher-Yang	

ESTIMATE REPAIR FOR Fong Kuan Yok (Feng Kunyu) 192 Punggol Central #16-315 Singapore 820192	ACCOUNT 14356 MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877
--	--

REGN. NO. SNG1624R	CHASSIS NO. LC0CE4DC3N0090400	REGN. DATE 15/07/2022	MODEL e6 (ME-2)	MILEAGE 9500
------------------------------	---	---------------------------------	---------------------------	------------------------

DESCRIPTION	VALUE
TO CONDUCT THIRD PARTY CLAIM AGAINST MS FIRST CAPITAL INS(SMB8038A). DOA:26.10.2022	0.00
TO REMOVE AND REPLACE REAR BUMPER.	600.00
TO PANEL BEAT/REPAIR REAR RIGHT FENDER.	300.00
TO REMOVE/REFIT/INSTALL REAR SENSOR.	80.00
TO CONDUCT BODY CAVITY PRESERVATION ON REAR RIGHT FENDER PANEL.	60.00
TO SPRAY PAINT REAR BUMPER AND REAR RIGHT FENDER PANEL. <i>600x2</i>	1,200.00
TO REMOVE AND REPLACE REAR RIGHT RIM WITH BALANCING.	60.00
TO SPRAY PAINT REAR RIGHT ALLOY RIM TO GLOSS BLACK.	200.00
TO CONDUCT ECU RE-PROGRAMMING AND CLEAR OF FAULT CODES TO ENSURE PROPER FUNCTION .(NETT)	600.00
SUNDRIES	20.00

Total Labour 1: **3,540.00**

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
12260724-00	REAR BUMPER UPPER BODY	1	895.00	10.00	805.50
11931334-00	REAR BUMPER LOWER BODY	1	235.00	10.00	211.50
11816555-00	REAR BUMPER BRACKET, LF	1	14.00	10.00	12.60
11816582-00	REAR BUMPER BRACKET,LR	1	29.00	10.00	26.10
11816583-00	REAR BUMPER BRACKET,RF	1	14.00	10.00	12.60
11816584-00	REAR BUMPER BRACKET,RR	1	29.00	10.00	26.10
12697828-00	REAR BUMPER LOWER BRACKET	2	238.00	10.00	428.40
12669990-00	ALUMINUM ALLOY WHEEL	1	682.00	10.00	613.80

Total Parts : **2,136.60**

Auto

Division of Vantage Automotive Limited)
Business Registration No. 53399829L GST Registration No. M2-0000551-1

BYD

305 Alexandra Road
159942 Singapore
Tel : 6376 8833
Fax : 6477 7398

GST Registration No. M2-0000551-1

ESTIMATE



Estimate No.	Date Estimated	Page No.
BY 5558	27/10/2022	2 of 2
	Prepared By	
	Clement Chia Cher-Yang	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNG1624R	LC0CE4DC3N0090400	15/07/2022	e6 (ME-2)	9500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue
Hp 90010068
4 days
31/10/22 @ 1030
Resy before paint

2860.00
805.50
3665.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Customer Name & Signature / Company Stamp	Date	Labour 1	S\$	3,540.00
		Parts	S\$	2,136.60
		Labour 2	S\$	0.00
		Excess	S\$	0.00
		Total GST @ 7%	S\$	397.36
		Grand Total	S\$	6,073.96

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.