



**ESTIMATE**

LEON TEO  
 BLK 15 MARINE TERRACE #12-02  
 Singapore 440015  
 Contact No : 92329611

Code : E22100011  
 Date In : 27/10/2022  
 Vehicle No. : SGF44J  
 Model : B.M.W. , 520I 2.0L AT D  
 Chassis No. : WBAXG12040DX53193

**Parts and Labour Assessment**

Description	Qty	Unit Price	Amount
<b>Parts &amp; Services</b>			
FRONT FENDER RH (REPAIR)	1.00	0.00	0.00
FRONT FENDER INNER SHIELD RH <i>X NN</i>	1.00	172.50	172.50
FRONT BUMPER SENSOR RH <i>— Mis</i>	1.00	232.40	232.40
FRONT REINFORCEMENT BEAM <i>X</i>	1.00	452.40	452.40
FRONT LOWER ARM RH <i>X</i>	1.00	252.10	252.10
FRONT KNUCKLE ARM RH <i>X</i>	1.00	371.30	371.30
FRONT WHEEL HUB RH <i>X</i>	1.00	621.40	621.40
FRONT ABSORBER RH <i>X</i>	1.00	372.10	372.10
FRONT HEADLAMP CONTROL MODULE RH <i>?</i>	1.00	532.40	532.40
FRONT BONNET <i>— BT 1985.60</i>	1.00	1,523.20	1,523.20
FRONT HEADLAMP RH <i>— CAA 2150.00</i>	1.00	2,235.20	2,235.20
FRONT BUMPER TOW COVER	1.00	62.30	62.30
FRONT BUMPER NOZZLE SPRAY COVER <i>— Mis</i>	1.00	74.30	74.30
FRONT BUMPER NOZZLE SPRAY	1.00	152.40	152.40
FRONT BUMPER RETAINER <i>X B — Cut @98.60</i>	2.00	154.20	308.40
FRONT BUMPER <i>— Re 1548.90</i>	1.00	1,423.20	1,423.20
Subtotal Before Discount S\$			8,785.60
0% Discount S\$			439.25
<b>Subtotal S\$</b>			<b>8,346.35</b>
FRONT BUMPER CLIPS SET	1.00	30.00	30.00
<b>Subtotal S\$</b>			<b>30.00</b>
<b>Parts &amp; Services Total S\$</b>			<b>8,376.35</b>
<b>Labour</b>			
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING	1.00	0.00	0.00
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1.00	1,000.00	1,000.00
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	1.00	1,000.00	1,000.00
Subtotal S\$			2,000.00
<b>Labour Total S\$</b>			<b>2,000.00</b>

LKK Auto Consultants hence notify the insurer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification allowed  
 • Our liability is limited to the amount surveyed and is subject to the surveyor's report and is acknowledged by the user

*5 Days.  
 Lump sum repair  
 After repair photos  
 Gm @ car - 82 88 02 82  
 28/10/22*

**Parts & Services Total S\$ 8,376.35**  
**Labour Total S\$ 2,000.00**  
**Grand Total S\$ 10,376.35**