

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : SNG 1790T

Made : B.M.W.

Model : 325i Coupe XL

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 1,349.70	\$ X 1,349.70
2	Front Bumper Side Retainer Rh	1	\$ 27.79	\$ X 27.79
3	Front Headlamp Assembly RH	1	\$ 2,634.18	\$ X 2,634.18
4	Front Fender RH	1	\$ 984.09	\$ X 984.09
5	Front Fender Signal Lamp RH	1	\$ 97.10	\$ X 97.10
6	Front Fender Inner Cowling RH	1	\$ 231.80	\$ X 231.80
7	Front Door Side Mirror RH	1	\$ 481.70	\$ X 481.70
8	Front Door Side Mirror Cover RH	1	\$ 116.10	\$ X 116.10
9	Front Door Side Mirror Glass RH	1	\$ 207.20	\$ X 207.20
10	Front Door Side Mirror Motor RH	1	\$ 406.30	\$ X 406.30
11	Front Door RH	1	\$ 1,236.60	\$ 66- 1,236.60
12	Front Door Hinge Upper RH	1	\$ 85.70	\$ X 85.70
13	Front Door Hinge Lower RH	1	\$ 91.30	\$ X 91.30
14	Front Door Check RH	1	\$ 75.30	\$ X 75.30
15	Front Door Seal RH	1	\$ 138.00	\$ X 138.00
16	Front Door Outer Window Moulding RH	1	\$ 123.40	\$ X 123.40
17	Front Door Inner Window Moulding RH	1	\$ 69.95	\$ X 69.95
18	Front Door Outer Handle RH	1	\$ 114.90	\$ X 114.90
19	Front Door Lock RH	1	\$ 396.15	\$ X 396.15
20	Front Door Lock Striker RH	1	\$ 21.75	\$ X 21.75
21	Front Door Inner Trim Board RH	1	\$ 1,074.65	\$ ana 1,074.65
22	Front Door Regulator RH	1	\$ 538.55	\$ X 538.55
23	Front Door Power Window Motor RH	1	\$ 742.60	\$ X 742.60
24	Rear Fender RH	1	\$ 1,524.65	\$ 66- 1,524.65
25	Front Shock Absorber RH	1	\$ 612.45	\$ X 612.45
26	Front Knuckle Arm RH	1	\$ 698.02	\$ X 698.02
27	Front Knuckle Arm Bearing RH	1	\$ 438.00	\$ X 438.00
28	Front Lower Arm RH	1	\$ 380.00	\$ X 380.00
29	Front Upper Arm RH	1	\$ 365.00	\$ X 365.00
30	Front Control Arm RH	1	\$ 323.64	\$ X 323.64
Rocker panel garnish RH ana				
Parts Sub Total :				\$ 15,586.57
5% Discount				\$ 779.33

PARTS TOTAL : \$ 14,807.24

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Bumper Clips - Set	1	\$ 50.00	\$ X 50.00
2	Front Fender Inner Cowling RH Clips - Set	1	\$ 50.00	\$ X 50.00
3	Front Door Inner Trim Board RH Clips - Set	1	\$ 50.00	\$ X 50.00
4	Front Fender RH Sealant	1	\$ 150.00	\$ 400 X 150.00
5	Front Door RH Sealant	1	\$ 150.00	\$ X 150.00
6	Rear Fender RH Sealant	1	\$ 150.00	\$ 400 X 150.00
7	Front Wheel Rim RH	1	\$ 1,200.00	\$ X 1,200.00
8	Front Tyre RH	1	\$ 500.00	\$ X 500.00
SPECIAL NETT TOTAL :				\$ 2,300.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 500 1,200.00
2	To Spray Paint Affected Areas	\$ 600 1,200.00
3	Wiring & Bulb Check	\$ X 100.00
4	To Transfer Front Door RH Mechanism	\$ 60 150.00
5	To apply anti rust on affected parts	\$ 40 100.00
6	To Remove & Refix Front Undercarriage	\$ X 350.00
7	To Conduct Four Wheel Alignment	\$ X 150.00
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ X 150.00
9	To Conduct Water Leak Test	\$ X 100.00
10	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
LABOUR TOTAL :		\$ 3,980.00

Tanjun 97815777
 WP' 27/10/22 @ 2157h
 1st meeting after repair
 Tanjun @ 16h auto in
 5 days
 - To check consistency of accident
 - To check part prices

PARTS TOTAL : \$ 14,807.24
 SPECIAL NETT TOTAL : \$ 2,300.00
 LABOUR TOTAL : \$ 3,980.00
 GRAND TOTAL : \$ 21,087.24