



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22010694/Uwy3e2 Date: 16/11/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBD 7241E	Veh. Inspected	SMX 3214A
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VC05/026575	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	27/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. X1 SDRIVE (A)	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	WBA32AA0805S51795	Colour	GREY
	Odometer	14549 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	CONTINENTAL	6 mm
	L/H Front Tyre	225/55 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/10/2022	Inspection Date	02/11/2022
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	