

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

Email : soonosanmotor@gmail.com

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:27/10/2022

Date: 31/10/2022

Estimate cost to repair ve: EY 3553K (Hyundai Elantra) claims under vel: GBK 2947Z

Not Authorized
28/10/22
L/C \$ 6900
5 days

1pce front right door	1832	\$ 1,993.20	Body DD	✓
1pce front door side mirror		638.60	R X	
2pcs front door hinges@\$41.10		42.20	11 X	
1pce front door weather strip		96.00	11 X	
1pce front door regulator		350.40	shut	✓
1pce front door outer top moulding		25.20	11 X	
1pce front right fender		1,227.70	Body DD	✓
1pce front fender inner shield		95.70	Torn	✓
10pce front fender inner shield inner clips@\$5		50.00	11	✓
1pce front fender lower mudflap		31.00	2	✓
1pce front bumper	474.40	974.40	Torn	✓
1pce front bumper side holder		38.00	Cne	✓
10pcs front bumper inner clips@\$5		50.00	11	✓
1pce front tow cover		21.00	11 X	
1pce front right fog lamp		365.10	Cne	✓
1pce front right top lamp		198.00	Cne	✓
1pce front fog lamp outer cover		115.40	Tw	✓
1pce front bumper reinforcement		695.80	3	✓
1pce front bumper side bracket		38.00	3	✓
1pce headlamp right		1,198.80	Cne	✓
1pce wirper tank		67.50	2	✓
1pce front door priller		998.00	R X	
1pce front windscreen outer rubber		57.10	11 X	
1pc front windscreen tape form		42.10	11 X	page 1

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

Email : soonsanmotor@gmail.com

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:27/10/2022

Date: 31/10/2022

Estimate cost to repair ve: EY 3553K (Hyundai Elantra) claims under vel: GBK 2947Z

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	\$ 9,409.20	
1pce front windscreen sunx sticker	300.00	11 X
1pce front windscreen inner sealant	120.00	11 X
1pce sport rim 015	300.00	601 /
1pce shock absorber 015	355	345.00
1pce lower arm 015	344.20	452.90
1pce front knuckle arm 015		396.00
1pce front hup arm 015		321.00
1pce front knuckle arm bearing 015		160.00
1pce drive shaft right 015		936.70
1pce steering rack & opion		1,046.90
	\$14,187.70	
Less 20%	2,837.54	
	\$11,350.16	
1set door vision (Assessor)	300.00	11 60 5/12
To towing accident place & IDAC	180.00	50
To rustproof	100.00	60
To remove/refit windscreen	140.00	11 X
To dismantle/renew door	200.00	60
To remove/refit dashboard	300.00	11 X
To dismantle/renew undercarriage	200.00	120
To computer wheel alignment before and after	150.00	100
To dismantle/renew accident portion	1,800.00	600
To spray paint	1,500.00	900

2-8383
202
670640
1950
865646925



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CASH	DATE	Oct 28, 2022 2:32:45 PM
FIRST NAME			
LICENSE NO.	EY 3553 K		
MILEAGE	58225		
MAKE	CUSTOM	MODEL	HYUNDAI ELANTRA (D84
NOTES			

Front Wheel SPECS DIAGNOSIS ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			-7.20				-7.20		
PARTIAL TOE	-0.50	0.00	0.50		-4.70		-2.50		-0.30		-6.80	
SET BACK	---	---	---			0°20"				0°20"		
CAMBER	-1°14"	-0°30"	0°14"		0°12"		-2°00"	1°48"	-0°16"		-1°56"	1°40"
CASTER	3°30"	4°30"	5°30"		4°30"		4°24"	0°04"	4°30"		4°24"	0°04"
KING-PIN	---	---	---		12°36"		13°04"	0°28"	12°36"		13°04"	0°28"
INCL ANGLE	---	---	---		12°24"		11°04"		12°20"		11°08"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel SPECS DIAGNOSIS ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			3.90				3.90		
PARTIAL TOE	---	---	---		2.90		1.00		2.90		1.00	
SET BACK	---	---	---			0°08"				0°08"		
CAMBER	---	---	---		-0°54"		-1°24"	0°28"	-0°54"		-1°24"	0°28"
THRUST ANGLE	-0°08"	0.00	0°08"			0°08"				0°08"		