

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT1653L**
 MODEL : **MIT-OUTLANDER**
 DATE OF ACCIDENT : 26.10.2022
 TIME OF ACCIDENT : 08:05 HRS

22	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 160.00	\$ 160.00	✓
23	REAR BUMPER <i>Del'd</i>	1	\$ 816.00	\$ 816.00	✓
24	REAR BUMPER SIDE ARCED GARNISH <i>new</i>	2	\$ 294.00	\$ 588.00	+
25	REAR BUMPER LAMP <i>new</i>	2	\$ 98.00	\$ 196.00	+
26	REAR BUMPER LAMP WIRE HARNESS <i>new</i>	1	\$ 387.00	\$ 387.00	+
27	REAR BUMPER LOWER CENTER GARNISH <i>Del'd</i>	1	\$ 269.00	\$ 269.00	✓
28	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 32.00	\$ 64.00	✓
29	TAIL LAMP <i>crack'd</i>	2	\$ 571.00	\$ 1,142.00	1012
30	TAIL LAMP PANEL <i>Rep's</i>	2	\$ 251.60	\$ 503.20	+
31	REAR FENDER INNER COWLING <i>new</i>	2	\$ 153.00	\$ 306.00	+
32	REAR FENDER INNER TRIM <i>crack'd</i>	2	\$ 927.00	\$ 1,854.00	1352
33	REAR END PANEL <i>Dented</i>	1	\$ 496.00	\$ 496.00	✓
34	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 146.00	\$ 146.00	✓
35	REAR FLOOR PANEL <i>Rep's</i>	1	\$ 714.00	\$ 714.00	+
36	REAR STORAGE COMPARTMENT GARNISH <i>crack'd</i>	1	\$ 455.00	\$ 455.00	✓
37	REAR TOOLS COMPARTMENT COVER <i>crack'd</i>	1	\$ 185.00	\$ 185.00	+
38	REAR STORAGE BOX <i>Del'd</i>	1	\$ 266.00	\$ 266.00	✓
39	REAR CHASSIS AND ABSORBER PANEL <i>Rep's</i>	2	\$ 105.00	\$ 210.00	+
40	REAR SPARE TYRE BRACKET <i>Best</i>	1	\$ 386.00	\$ 386.00	✓
41	REAR SPARE TYRE BRACKET HOLDER <i>new</i>	1	\$ 128.00	\$ 128.00	+

11498.90

10379.01

TOTAL PRICE \$ 17,469.00
 LESS 10% \$ 1,746.90
 SUB TOTAL PRICE \$ 15,722.10

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30.
3	REAR BUMPER SIDE ARCED GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	REAR BUMPER CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
6	TAILGATE EMBLEM 'C&C' <i>new</i>	1	\$ 180.00	\$ 180.00	60.
7	TAILGATE INNER TRIM (TOP) CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10
8	TAILGATE INNER TRIM (SIDE) CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10
9	TAILGATE INNER TRIM (LOWER) CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT1653L**
 MODEL : **MIT-OUTLANDER**
 DATE OF ACCIDENT : 26.10.2022
 TIME OF ACCIDENT : 08:05 HRS

10	TAILGATE WINDSCREEN SOLAR FLIM <i>me</i>	1	\$ 550.00	\$ 550.00	250
11	TAILGATE WINDSCREEN SEALANT <i>me</i>	1	\$ 80.00	\$ 80.00	40
12	TAILGATE WINDSCREEN INNER SHIELD <i>me</i>	1	\$ 60.00	\$ 60.00	30
13	TAILLAMP CLIP (SET) <i>me</i>	1	\$ 40.00	\$ 40.00	+
14	REAR FENDER INNER TRIM CLIP (SET) <i>me</i>	1	\$ 60.00	\$ 60.00	50
15	REAR FENDER INNER COWLING CLIP (SET) <i>me</i>	1	\$ 60.00	\$ 60.00	+
16	REAR END PANEL INSULATION SEAL <i>me</i>	1	\$ 150.00	\$ 150.00	60
17	REAR END PANEL TOP GARNISH CLIP (SET) <i>me</i>	1	\$ 50.00	\$ 50.00	10
18	REAR FLOOR PANEL INSULATION SEAL <i>me</i>	1	\$ 350.00	\$ 350.00	200
19	REVERSE SENSOR (SET) <i>me</i>	1	\$ 280.00	\$ 280.00	200
20	REVERSE CAMERA <i>me</i>	1	\$ 550.00	\$ 550.00	380
21	VIDEO RECORDER <i>me Missing</i>	1	\$ 850.00	\$ 850.00	580

1940 TOTAL \$ 3,850.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	1100
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1100
3	TUFF COAT	\$ 250.00	80
4	WIRING AND BULB CHECK	\$ 180.00	30
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	80
6	REMOVE AND REPLACE VIDEO RECORDER	\$ 80.00	50
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT1653L**
 MODEL : **MIT-OUTLANDER**
 DATE OF ACCIDENT : 26.10.2022
 TIME OF ACCIDENT : 08:05 HRS

9	REINSTALL AND RESET AUTO SYSTEM SENSOR	\$ 350.00	X
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	120
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 200.00	X

2740

TOTAL \$ 5,680.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,572.10
 TOTAL LABOUR COST : \$ 5,680.00
 TOTAL REPAIR COST : \$ 25,252.10

Adrian G
 1/s 27/10/22.
 07 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Total: (15025.10)

YOURS FAITHFULLY,

1/s: 112K

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

12K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: