

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 10.10.2022

TO : **INCOME** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SLP7465U**  
MODEL : **HONDA VEZEL**  
DATE OF ACCIDENT : 14.09.2022  
TIME OF ACCIDENT : 09:30 HRS

*Xiao Chun.*

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delud</i>	1	\$ 568.20	\$ 568.20
2	REAR BUMPER REFLECTOR <i>Ne n</i>	2	\$ 156.20	\$ 312.40
3	REAR BUMPER SIDE LH <i>Delud</i>	1	\$ 195.40	\$ 195.40
4	REAR BUMPER SIDE RETAINER <i>HH Ryd</i>	2	\$ 57.00	\$ 114.00
5	REAR FENDER AIR VENT LH <i>Ne n</i>	1	\$ 89.60	\$ 89.60
6	REAR FENDER COWLING LH <i>Ne n</i>	1	\$ 150.20	\$ 150.20
7	REAR FENDER ARCED GARNISH <i>At LH</i>	2	\$ 184.70	\$ 369.40
8	TAIL LAMP LH <i>Contd</i>	1	\$ 475.00	\$ 475.00
9	BUZZER <i>Ne n</i>	1	\$ 109.00	\$ 109.00
10	REAR FLOOR PANEL BOTTOM GARNISH <i>Ne n</i>	1	\$ 269.00	\$ 269.00

*1480.30*  
*1184.24*

TOTAL PRICE \$ 2,652.20  
LESS 20% \$ 530.44  
SUB TOTAL PRICE \$ 2,121.76

### SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00
2	TAIL LAMP CLIP (SET) <i>Ne n</i>	1	\$ 40.00	\$ 40.00
3	REAR FENDER INNER TRIM CLIP (SET) <i>Ne n</i>	1	\$ 60.00	\$ 60.00
4	REAR FENDER COWLING CLIP (SET) <i>Ne n</i>	1	\$ 60.00	\$ 60.00
5	REAR END PANEL TOP GARNISH CLIP (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00
6	REAR END PANEL INSULATION SEAL <i>Ne n</i>	1	\$ 150.00	\$ 150.00
7	REVERSE SENSOR (SET) <i>Ne n</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 660.00

*40*

TO : **INCOME** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLP7465U**  
 MODEL : **HONDA VEZEL**  
 DATE OF ACCIDENT : 14.09.2022  
 TIME OF ACCIDENT : 09:30 HRS

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	100
3	TUFF COAT	\$ 250.00	x.
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	x
5	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

300

**TOTAL \$ 2,780.00**

TOTAL PARTS COST : \$ 2,781.76  
 TOTAL LABOUR COST : \$ 2,780.00  
 TOTAL REPAIR COST : \$ 5,561.76

Adrian Cj  
 h/s 27/10/22.  
 03 Days

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

total: 152424  
 L/s: 1.2K

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: