



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CS3/CTI22010707/Gvy3 Date: 28/10/2022 Code: CTI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
<b>Insured Veh.</b>	GBL 427R	<b>Veh. Inspected</b>	SMK 1010C
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM22D207677/C02/GBL427R/ TANCHC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JACQUELINE TAN	<b>Assign Date</b>	28/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
<b>Accident Date</b>	26/10/2022	<b>Inspection Date</b>	28/10/2022
<b>Survey held at</b>	HONG MOTOR SERVICES BLK 5035 ANG MO KIO IND PARK 2 #01-365 SINGAPORE 569538		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			