

133 New Bridge Road #11-02 Chinatown Point Singapore 059413 Tel: +65 6227-2469 Fax: +65 6225-2579

Email: law@dpco.com.sg

(UEN: 53130838C)

Daniel Poon Choon Kow

LL. B. (Hons), LLM

Our Ref: DP.sl.11983.22.TIMC

Your Ref:

Please quote our reference number when replying

Date: 26 October 2022

M/S MS FIRST CAPITAL INSURANCE LIMITED E-MAIL ONLY 16 RAFFLES OUAY (motorclaims@msfirstcapital.com.sq)

#42-00

SINGAPORE 048581

ATTN: MOTOR CLAIMS DEPARTMENT

DEAR SIRS.

PRE-REPAIR INSPECTION

YOUR INSURED VEHICLE REGISTRATION NO: SHB 89P ACCIDENT ON 22 OCTOBER 2022 INVOLVING FBS 7584L AND SHB 89P ALONG WOODLANDS AVENUE 4

We are instructed by IRWAN BIN HUSSIN to notify you of a road traffic accident on 22 October 2022 at about 17:30 along Woodlands Avenue 4 involving our client's vehicle registration number FBS 7584L and vehicle registration number SHB 89P driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of two (02) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a prerepair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

*Please contact workshop direct first before the Pre-repair inspection, so as to ensure the vehicle is in.

M/S TUNE IN MOTOR.COM BLK 1016 YISHUN INDUSTRIAL PARK A # 01-214

SINGAPORE 768758

ATTN: MS LINDA (6753-4818)

If we do not receive any agreement from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

c.c. M/S TUNE IN MOTOR.COM

FAX (6753-5850) ONLY