

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 08 Nov 2022

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|------------------|
| Vehicle No | : SNF8532G | Accident Date | : 23/10/2022 |
| Make | : MERCEDES-BENZ CLA200 | Policy No. | : MPC22A00136100 |
| Assignment Date | : 27/10/2022 | Excess | : S\$1,100.00 |
| Date of Inspection | : 28/10/2022 | Est. Duration of Repair | : 4 |
| Inspection At | : SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-------------------------------------|
| Repairer's Estimate (Gross) | :S\$ | 10,912.00 (inclusive supp \$704.00) |
| Revised Amount | :S\$ | 7,701.00 |
| Check Items (Estimated) | :S\$ | 363.00 |
| Total | :S\$ | 8,064.00 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 34,000.00 |
| COE / PARF Rebate | :S\$ | 22,698.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 11,302.00 |

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve on supplementary.