



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010714/Tqy3e2	
			Date: 19/05/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6126R	Veh. Inspected	SFT 6666M
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/22/2079	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	28/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VELLFIRE	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	AGH300230329	Colour	WHITE
	Odometer	17932 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	TOYO	6 mm
	L/H Front Tyre	235/50 R18	TOYO	6 mm
	R/H Rear Tyre	235/50 R18	TOYO	6 mm
	L/H Rear Tyre	235/50 R18	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/10/2022	Inspection Date	31/10/2022
	Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KKAU BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	