



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

SFT6666M Toyota Vellfire

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,928.30 <i>de- 1217</i>
2	1	Rear bumper left bracket	\$ 122.60 <i>x nn</i>
3	1	Rear bumper right bracket	\$ 122.60 <i>de -</i>
4	1	Rear bumper tow cover	\$ 98.00 <i>ant</i>
5	2	Rear air vent	\$ 190.00 <i>x 7 nn</i>
6	2	Bumper corner light	\$ 400.00 <i>x nn</i>
7	1	Rubber Seal	\$ 280.00 <i>dis- 180</i>
8	1	Rear Tailgate	\$ 2,250.00 <i>bt- 1768</i>
9	2	Tailgate side trim holder with seals	\$ 800.00 <i>x</i>
10	1	Tailgate lock	\$ 350.00 <i>x nn</i>
11	1	Lock hook	\$ 95.00 <i>x</i>
12	1	Lower skirt area trim	\$ 150.00 <i>x</i>
13	1	Keyless with bracket	\$ 380.00 <i>nn- 215</i>
14	1	Bumper side guard cover trim RH	\$ 550.00 <i>de- 295.30</i>
15	1	Tailgate light left	\$ 1,250.00 <i>x</i>
16	1	Tailgate light right	\$ 1,250.00 <i>x nn</i>
17	1	Middle chrome	\$ 380.00 <i>x</i>
18	1	Logo	\$ 120.00 <i>nn- 90</i>
19	2	Bumper side molding	\$ 190.00 <i>x</i>
20	1	Spare tyre set	\$ 950.00 <i>x</i>
21	1	Spare tyre trim holder /base	\$ 350.00 <i>x nn</i>
22	1	Spare tyre cover	\$ 200.00 <i>x</i>
24	1	Rear end panel	\$ 950.00 <i>bt- 820</i>
25	1	Sensor harness	\$ 350.00 <i>dis- 244</i>
Sub-total Parts			\$ 13,706.50 <i>5049.90</i>

25/- 3787.42



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

SFT6666M Toyota Vellfire

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 100.00 <i>30 nec ✓</i>
2	8	Rear end lower panel top garnish clips	\$ 80.00 <i>x nn</i>
3	1	Rear side panel sealant	\$ 120.00 <i>40 nec</i>
4	8	Rear fender inner trim board clips	\$ 80.00 <i>x</i>
5	6	Side guard cover clips	\$ 100.00 <i>x</i>
6	10	Rear end side panel clips	\$ 80.00 <i>x nn</i>
7	8	Rear no plate with garnish	\$ 80.00 <i>x</i>
8	10	Tailgate side cover clips	\$ 100.00 <i>x</i>
9	20	Tailgate inner cover trim clips	\$ 120.00 <i>x</i>
10	1/4	Rear sensor	\$ 800.00 <i>nn- 200</i>
Sub total special nett			\$ 1,660.00 <i>270</i>



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SFT6666M Toyota Vellfire

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 100.00 40
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 200.00 50.
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 1,800.00 700
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear end panel side cover x2, fender touch up, repray the spray tyre	\$ 2,000.00 900
5	To check rear light wiring	\$ 100.00 40
6	To apply anti rust proofing to affected area, spare tyre area full of water	\$ 300.00 30
7	To remove and dry the floor carpet	\$ 150.00 80.
8	To remove, wash and dry spare tyre cover	\$ 80.00 x un
9	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 150.00 60.
10	To remove last row seats to facilitate the rear work-spare tyre water	\$ 200.00 80.
11	Ceremic coating for affected area	\$ 350.00 x un
12	Remove and install both fender internal trim to facilitate works	\$ 150.00 x un
13	To remove and install rear camera	\$ 80.00 30.
14	Transferring tailgate and rear end wiring harness for proper	\$ 150.00 X
15	Rear water test-necessary	\$ 150.00 X
16	Check rear bumper wiring and sensors harness	\$ 80.00 X
17	Computer reset system / after accident	\$ 250.00 X
16	Paint protection coating for accident affected areas	\$ 350.00 X

Tanjiun 99495749
 WP 31/10/22 e
 L/S Romy after repair
 06days
 tanjiun @ Wharnton.

3787.42
 270
 2010
 6067.42

4544850, 6days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: