



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |   |            |
|--|--|---|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705  |  | Ref: CS/SMR22010717/Rqy3m4<br>Date: 01/03/2023<br>Code: SMR |            |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |   |            |
| Insured Veh.   | SHF 207U   | Veh. Inspected  | SDQ 8822E  |
| Policy No.   |  | Coverage (\$)   | 0.00       |
| Claim No.  | TAX/10/22/2030   | Excess (\$)   | 0.00       |
| Assign From  | HUA YEN  | Assign Date   | 28/10/2022 |
| 2. Vehicle Particulars & Condition   |  |   |            |
| Make & Model   | MERCEDES BENZ S320L  | c.c   | 2996       |
| Engine No.   | HIDDEN   | Year of Reg.  | 2018       |
| Chassis No.  | WDD2221622A422768  | Colour  | BLUE       |
| Odometer   | 53936 KM   | Steering  | IN ORDER   |
| Brakes   | IN ORDER   | Modification  | SPORTS RIM |
| General  | FAIR   |   |            |
| 3. Conditions of Tyres   |  |   |            |
|  | Size   | Make  | Balance    |
| R/H Front Tyre   | 245/40 ZR20  | MICHELIN  | 6 mm       |
| L/H Front Tyre   | 245/40 ZR20  | MICHELIN  | 6 mm       |
| R/H Rear Tyre  | 245/40 ZR20  | MICHELIN  | 6 mm       |
| L/H Rear Tyre  | 245/40 ZR20  | MICHELIN  | 6 mm       |
| 4. Description of Damages  |  |   |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |   |            |
| 5. General Information   |  |   |            |
| Accident Date  | 09/10/2022   | Inspection Date   | 31/10/2022 |
| Survey held at   | CYCLE & CARRIAGE INDUSTRIES PL<br>188 PANDAN LOOP<br>SINGAPORE 128378<br>(MERCEDES-BENZ) |   |            |
| 5a. Remarks  |  |   |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |   |            |
| 5b. Estimate Days of Repair  |  |   |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 3 Working Days  |            |