



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDQ8822E

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 60151
Reg No/Reg Date SDQ8822E / 13/11/2018
Date In/Mileage / 0
Chassis No WDD2221622A422768
Engine No 27682430899422
Make/Model MB/MB S 320 SEDAN LONG
Colour/Trim 028 890 Cavansite B/ 048 814 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	10/10/2022/ 13:10	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPN SUN POLICY NO/ACC DATE : 1800133737 // 09-10-2022 DRIVE IN: 10-10-2022 // TP CAR NO: SHF2070 (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				480.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960 1440.00
A BPIRES RESPRAY REAR BUMPER				800 1000.00
M REAR BUMPER	1.00	2271.23	00.00	2271.23
M LH/R BUMPER GARNISH	1.00	137.59	00.00	137.59
M RH/R BUMPER GARNISH	1.00	137.59	00.00	137.59
M REAR BUMPER BOTTOM PANEL	1.00	610.00	00.00	610.00
M CT/R BUMPER BOTTOM PANEL GARNISH	1.00	138.38	00.00	138.38
M RH/R BUMPER BOTTOM PANEL GARNISH	1.00	178.62	00.00	178.62
M CT/R BASIC MOUNTING FOR BUMPER	1.00	155.06	00.00	155.06
M LH/R BASIC MOUNTING FOR BUMPER	1.00	102.22	00.00	102.22
M RH/R BASIC MOUNTING FOR BUMPER	1.00	102.60	00.00	102.60
M CT/R PARKING SENSOR	4.00	195.43	00.00	781.72
M CT/R PARKING SENSOR SEAL	4.00	7.10	00.00	28.40
M REAR CROSS MEMBER	1.00	1352.69	00.00	1352.69

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Alan
49001068 w/prejudice
3 days
31/10/22 @ 1350
Resy before print

Confirmed & accepted by

Authorized signatory and company stamp

Nett 8,916.10
7% GST on 8916.10 624.13
Total Payable 9,540.23

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg