



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SDQ8822E

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT  
6 RAFFLES QUAY  
#21-00  
SINGAPORE 048580  
65073848

Vehicle & Document Information

WIP No	60151
Reg No/Reg Date	SDQ8822E / 13/11/2018
Date In/Mileage	0 / 0
Chassis No	WDD2221622A422768
Engine No	27682430899422
Make/Model	MB/MB S 320 SEDAN LONG
Colour/Trim	028 890 Cavansite B/ 048 814 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
------------	-------	-------------------	-----	----------

WF001862 Credit 10/10/2022/ 13:10 AQ 305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN				
POLICY NO/ACC DATE : 1800133737 // 09-10-2022				
DRIVE IN: 10-10-2022 // TP CAR NO: SHF2070 (FIRST CAPITAL INSURANCE)				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
A BPILAB				480.00
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				
A BPILAB				1440.00
REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				
A BPIRES			0.07	1000.00
RESPRAY REAR BUMPER				
M REAR BUMPER	1.00	2271.23	00.00	2271.23
M LH/R BUMPER GARNISH	1.00	137.59	00.00	137.59
M RH/R BUMPER GARNISH	1.00	137.59	00.00	137.59
M REAR BUMPER BOTTOM PANEL	1.00	610.00	00.00	610.00
M CT/R BUMPER BOTTOM PANEL GARNISH	1.00	138.38	00.00	138.38
M RH/R BUMPER BOTTOM PANEL GARNISH	1.00	178.62	00.00	178.62
M CT/R BASIC MOUNTING FOR BUMPER	1.00	155.06	00.00	155.06
M LH/R BASIC MOUNTING FOR BUMPER	1.00	102.22	00.00	102.22
M RH/R BASIC MOUNTING FOR BUMPER	1.00	102.60	00.00	102.60
M CT/R PARKING SENSOR	4.00	195.43	00.00	781.72
M CT/R PARKING SENSOR SEAL	4.00	7.10	00.00	28.40
M REAR CROSS MEMBER	1.00	1352.69	00.00	1352.69

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett	8,916.10
7% GST on	8916.10
	624.13
<b>Total Payable</b>	<b>9,540.23</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg