



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDQ8822E

Finalization

Vehicle & Document Information

MS FIRST CAPITAL INSURANCE LIMITED
MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Rasul

WIP No 60151
Reg No/Reg Date SDQ8822E / 13/11/2018
Date In/Mileage 31/10/2022/ 53936
Chassis No WDD2221622A422768
Engine No 27682430899422
Make/Model MB/MB S 320 SEDAN LONG
Colour/Trim 028 890 Cavansite B/ 048 814 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	08/12/2022/ 19:43	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPN SUN POLICY NO/ACC DATE :1800133737 // 09-10-2022 DRIVE IN:10-10-2022 // TP CAR NO:SHF207U (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY:31-10-2022 // LKK RASUL BY/AUTHORIZED ON :ANA MAGNAYE // 17-10-2022				480.00
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				960.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				800.00
A BPIRES RESPRAY REAR BUMPER			0.05	800.00
X REAR BUMPER	1.00	2271.23	00.00	2271.23
X LH/R BUMPER GARNISH	1.00	137.59	00.00	137.59
X RH/R BUMPER GARNISH	1.00	137.59	00.00	137.59
X REAR BUMPER BOTTOM PANEL	1.00	610.00	00.00	610.00
X CT/R BUMPER BOTTOM PANEL GARNISH	1.00	138.38	00.00	138.38
X RH/R BUMPER BOTTOM PANEL GARNISH	1.00	178.62	00.00	178.62

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 5,713.41
7% GST on 5713.41 399.94
Total Payable 6,113.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg