



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLV5094M NISSAN SYLPHY 1.6

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Side mirror assy RH / BR		388.00	
1	Side mirror cover RH / mis		90.00	
1	Rear door RH x R		1016.00	X
1	Rear door window pillar top sticker RH X nn		39.00	X
1	Rear door window pillar side sticker RH X nn		39.00	X
1	Rear door handle bar (long) / nt		284.00	
1	Rear door handle bar (short) / nt		52.00	
1	Rear fender RH / DO		1533.00	
1	Tail lamp RH / BR		359.00	
1	Tail lamp clips RH x / BR		5.00	
1	Pump fuel cover / DO		94.00	
1	Front door RH (Repair refer to labour) X nn		0.00	X
Part Items Total:			3899.00	
			-30%	
			-1169.70	
			2729.30	
SPECIAL NETT ITEMS				
1	Rear fender RH sealant / n/c		40 60.00	
1	Rear windscreen sealant / n/c		40 60.00	
SN Items Total:			120.00	
Total Parts			2849.30	

Steve (LKK)

7/11/22, 10.00h

m n

L/S

My AL 4, 6 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLV5094M NISSAN SYLPHY 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	700
3	To perform anti-rust treatment on affected areas	60.00	30
4	To remove and refit rear windscreen	100.00	/
5	To remove and replace rear door RH fitting, trimmings, garnish, window glass and lock mechanism	120.00	X 80
6	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	30
7	To remove and refit rear seat in order to repair	100.00	50
8	To remove and refit roots lining & upholster garnish	100.00	50
9	To remove and refix rear quarter glass RH	120.00	80
			1840
	Labour Total :	2890.00	
	TOTAL (PARTS & LABOUR):	5739.30	

= 3873.50

L/S - 3098.80

= 3100