

ASS. R. = U.B. *1/2*

REF:

CS/CT 12210771/ Tug3:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp. at Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehl: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$111K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5JJ5259S Yr Regn: 2008, Sep

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1794

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 183566 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STPER12W305000561

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoperative / Jammed / Leaked / Burnt or

Brake: Inoperative / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 225/45R17

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRI / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 28/10/22

Survey held at Prompt. Auto.

Des. of Damages Ft / Rear / O/S / N/S / WC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

Rep. Format: _____

Lump Sum / I.B.J. /

Prompt Auto Solutions Pte Ltd

8 Kaki Bukit Avenue 4 #02-37 @ Kaki Bukit (415875)

Tel: 97319322 - ROY CHAK

E-mail: promptautosolutions@gmail.com

TO : ATTENTION : VEHICLE DETAILS VEHICLE NO: SJJ5259S MAKE / MODEL: Toyota Wish CHASSIS NO: JTDER12W303000561	REPAIR ESTIMATE DATE : JOB TYPE : THIRD PARTY ACCIDENT DETAILS DATE : TIME :
---	---

S/N	DESCRIPTIONS	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Tailgate	1	\$ 1,284.00	\$ <i>ht</i> 1,284.00
2	Tailgate windscreen glass lower rubber moulding	1	\$ 45.00	\$ <i>ue</i> 45.00
3	Tailgate windscreen glass upper rubber moulding	1	\$ 45.00	\$ <i>ue</i> 45.00
4	Tailgate windscreen glass RH side rubber moulding	1	\$ 39.00	\$ <i>ue</i> 39.00
5	Tailgate windscreen glass LH side rubber moulding	1	\$ 39.00	\$ <i>ue</i> 39.00
6	Tailgate centre emblem	1	\$ 89.00	\$ <i>ue</i> 89.00
7	Tailgate centre chrome moulding	1	\$ 302.00	\$ <i>ue</i> 302.00
8	Tailgate centre chrome moulding clips	1set	\$ 40.00	\$ <i>ue</i> 40.00
9	Tailgate lock	1	\$ 455.00	\$ <i>ht</i> 455.00
10	Tailgate lock catch	1	\$ 55.00	\$ <i>ht</i> 55.00
11	Tailgate inner trim board	1	\$ 567.00	\$? 567.00
12	Tailgate inner trim board clips	1set	\$ 60.00	\$? 60.00
13	Tailgate opener switch button sensor	1	\$ 156.00	\$? 156.00
14	Tailgate RH lamp	1	\$ 440.00	\$ 440 X 440.00
15	Tailgate RH lamp gasket	1	\$ 39.00	\$ X 39.00
16	Tailgate LH lamp	1	\$ 440.00	\$ 440 X 440.00
17	Tailgate LH lamp gasket	1	\$ 39.00	\$ X 39.00
18	Tailgate weatherstrip	1	\$ 38.00	\$? 388.00
19	Tailgate wiper motor	1	\$ 532.00	\$ X 532.00
20	Tailgate RH number plate lamp	1	\$ 82.00	\$ X 82.00
21	Tailgate LH number plate lamp	1	\$ 82.00	\$ X 82.00
22	Tailgate RH absorber stay	1	\$ 216.00	\$? 216.00
23	Tailgate LH absorber stay	1	\$ 216.00	\$? 216.00
24	Rear bumper	1	\$ 732.00	\$ <i>de</i> 732.00
25	Rear bumper clips	1set	\$ 60.00	\$ <i>ue</i> 30 60.00
26	Rear bumper RH reverse sensor holder	1	\$ 44.00	\$ X 44.00
27	Rear bumper RH reverse sensor	1	\$ 256.00	\$ <i>nw</i> 256.00
28	Rear bumper LH reverse sensor holder	1	\$ 44.00	\$ X 44.00
29	Rear bumper LH reverse sensor	1	\$ 256.00	\$ <i>nw</i> 256.00
30	Rear bumper RH reflector	1	\$ 78.00	\$ X 78.00
31	Rear bumper LH reflector	1	\$ 78.00	\$ X 78.00
32	Rear bumper RH bracket	1	\$ 87.00	\$ <i>de</i> 87.00
33	Rear bumper LH bracket	1	\$ 87.00	\$ <i>de</i> 87.00
34	Rear bumper RH side retainer	1	\$ 112.00	\$ <i>de</i> 112.00
35	Rear bumper LH side retainer	1	\$ 112.00	\$ <i>de</i> 112.00
36	Rear bumper RH side bracket	1	\$ 72.00	\$ <i>de</i> 72.00
37	Rear bumper LH side bracket	1	\$ 72.00	\$ <i>de</i> 72.00
38	RH taillamp	1	\$ 664.00	\$ <i>de</i> 664.00
39	RH taillamp gasket	1	\$ 54.00	\$ X 54.00
40	RH taillamp panel	1	\$ 172.00	\$ <i>Ry</i> 172.00

41	LH taillamp					
42	LH taillamp gasket	1	\$	664.00	\$ cut/	664.00
43	LH taillamp panel	1	\$	54.00	\$ neu/	54.00
44	End panel	1	\$	172.00	\$ bui/	172.00
45	End panel inner garnish	1	\$	568.00	\$ bt/	568.00
46	End panel inner garnish clips	1	\$	298.00	\$ de/	298.00
47	End lower panel	1set	\$	50.00	\$ neu/	50.00
48	End panel antenna sensor	1	\$	389.00	\$ bt/	389.00
49	Rear RH fender	1	\$	199.00	\$?	199.00
50	Rear RH fender glass with rubber seal	1	\$	987.00	\$ Ry	987.00
51	Rear RH fender inner trim	1	\$	532.00	\$?	532.00
52	Rear RH fender inner trim clips	1	\$	803.00	\$?	803.00
53	Rear RH fender splash shield	1set	\$	60.00	\$?	60.00
54	Rear RH fender splash shield clips	1	\$	132.00	\$?	132.00
55	Rear RH fender inner air duct	1set	\$	40.00	\$ x	40.00
56	Rear LH fender	1	\$	154.00	\$ x	154.00
57	Rear LH fender glass with rubber seal	1	\$	987.00	\$ bui/	987.00
58	Rear LH fender inner trim	1	\$	532.00	\$ neu/	532.00
59	Rear LH fender inner trim clips	1	\$	803.00	\$?	803.00
60	Rear LH fender splash shield	1set	\$	60.00	\$?	60.00
61	Rear LH fender splash shield clips	1	\$	132.00	\$ de/	132.00
62	Rear LH fender inner air duct	1set	\$	40.00	\$ de/	40.00
63	Rear compartment panel trim garnish	1	\$	154.00	\$ de/	154.00
64	Rear compartment panel trim board cover	1	\$	477.00	\$?	477.00
65	Spare tyre carriage	1	\$	783.00	\$?	783.00
66	Exhaust silencer	1	\$	367.00	\$ mis/	367.00
67	Exhaust silencer gasket	1	\$	1,109.00	\$ bt/	1,109.00
68	Exhaust silencer rubber mountings	1	\$	109.00	\$ neu/	109.00
		1	\$	128.00	\$ de/	128.00
	Bonnet	1	\$	883.00	\$ bt/	883.00
	Bonnet chrome moulding	1	\$	241.00	\$ cut/	241.00
	Bonnet emblem	1	\$	89.00	\$ de/	89.00
	Bonnet RH hinge	1	\$	101.00	\$ bt/	101.00
	Bonnet LH hinge	1	\$	101.00	\$ bt/	101.00
	Bonnet lock	1	\$	189.00	\$ bt/	189.00
	Front bumper	1	\$	566.00	\$ de/	566.00
	Front bumper RH side retainer	1	\$	67.00	\$ de/	67.00
	Front bumper LH side retainer	1	\$	67.00	\$ de/	67.00
	Front bumper LH fog lamp cover	1	\$	55.00	\$?	55.00
	Front bumper RH fog lamp cover	1	\$	55.00	\$?	55.00
	Front bumper reinforcement	1	\$	281.00	\$ bt/	281.00
	Front bumper inner sponge	1	\$	119.00	\$ de/	119.00
	Front bumper centre lower grille	1	\$	89.00	\$ de/	89.00
	RH headlamp assy	1	\$	902.00	\$ neu/	902.00
	LH headlamp assy	1	\$	902.00	\$ neu/	902.00
	Support panel	1	\$	789.00	\$ bt/	789.00
	Support panel top garnish	1	\$	188.00	\$ de/	188.00
	Support panel top garnish clips	1set	\$	50.00	\$ neu/	50.00
	Front brace panel	1	\$	91.00	\$ bt/	91.00
	Front RH fender	1	\$	355.00	\$ bt/	355.00
	Front RH fender splash shield	1	\$	98.00	\$?	98.00
	Front RH fender splash shield clips	1set	\$	50.00	\$?	50.00
	Front LH fender	1	\$	355.00	\$ bt/	355.00
	Front LH fender splash shield	1	\$	98.00	\$?	98.00
	Front LH fender splash shield clips	1set	\$	50.00	\$?	50.00
	Front grille	1	\$	202.00	\$ neu/	202.00
	Front grille clips	1set	\$	40.00	\$ neu/	40.00
	Aircon condenser	1	\$	1,510.00	\$?	1,510.00

Aircon suction pipe				
Aircon discharge pipe	1	\$	346.00	\$? 346.00
Aircon liquid pipe	1	\$	355.00	\$? 355.00
Radiator assy	1	\$	503.00	\$? 503.00
Radiator fan assy	1	\$	1,716.00	\$? 1,716.00
	1	\$	753.00	\$? 753.00

TOTAL PRICE: \$ 31,669.00
LIST LESS 25%: \$ 7,917.25
SUB TOTAL PRICE: \$ 23,751.75

S/N	DESCRIPTIONS	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	Tailgate windscreen glass sealant	1	\$ 80.00	\$ 40.00/ 80.00
2	Tailgate windscreen glass inner seal	1	\$ 60.00	\$ 30.00/ 60.00
3	Tailgate reverse camera	1	\$ 850.00	\$ X 850.00
4	Rear RH fender glass sealant	1	\$ 70.00	\$ X 70.00
5	Rear RH fender glass inner seal	1	\$ 50.00	\$ X 50.00
6	RearRH fender joint sealant	1	\$ 70.00	\$ X 70.00
7	Rear LH fender glass sealant	1	\$ 70.00	\$ ne/ 70.00
8	Rear LH fender glass inner seal	1	\$ 50.00	\$ ne/ 50.00
9	Rear LH fender joint sealant	1	\$ 70.00	\$ ne/ 70.00
10	Rear number plate	1	\$ 80.00	\$ ant/45 80.00
11	Front number plate	1	\$ 70.00	\$ car/45 70.00
12	Radiator coolant	1	\$ 80.00	\$? 80.00

S/N TOTAL PRICE: \$ 1,600.00

S/N	DESCRIPTIONS		PRICE
	(Rear portion)		
1	Labour charges on affected areas and replaced parts as listed	1200	\$ 2,800.00
2	Re-spray affected areas and parts	1200	\$ 2,000.00
3	Check wiring and lighting system	30	\$ 100.00
4	Apply anti rust chemical coating	30	\$ 180.00
5	Remove and refit tailgate windscreen glass for repair	120	\$ 280.00
6	Remove and replace tailgate reverse camera for repair	30	\$ 180.00
7	Remove and replace tailgate inner components for repair	60	\$ 280.00
8	Remove and repalce rear bumper reverse sensors for repair	30	\$ 100.00
9	Remove and replace rear inner garnish and trims for repair	60	\$ 280.00

10	Remove and replace exhaust silencer and gasket for repair (front portion)	60	\$	180.00
1	Labour charges on affected areas and replaced parts as listed	1000	\$	2,500.00
2	Re-spray affected areas and parts	1000	\$	2,000.00
3	Check wiring and lighting system	50	\$	100.00
4	Apply anti rust chemical coating	50	\$	180.00
5	Remove and replace aircon condenser and pipes	100	\$	300.00
6	Remove and replace radiator assy, hoses and fan assy	100	\$	300.00
LABOUR TOTAL PRICE: \$				11,760.00

ESTIMATE REPORT

TOTAL PARTS PRICE	:	\$	25,351.75
TOTAL LABOUR PRICE	:	\$	11,760.00
TOTAL AMOUNT	:	\$	<u>37,111.75</u>

APPROVED DETAILS

NO. OF REPAIR DAYS	:	
P & P OR LUMP SUM	:	
SURVEYED BY	:	
CONTACT NUMBER	:	
E-MAIL	:	

Tauphu 97495749
 - WP - 28/10/22 04pm. 14 days
 1/5 Resurvey after repair
 Repair limit \$8000
 Total loss not economical to repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: