

BHAGLAAX

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

LKK Auto Consultancy hence notified
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is allowed "Without Prejudice"
 • Illegal modification is allowed
 • Elementary repair must be resurveyed
 • To be approved from Insurance Company
 signed by _____

Repair Estimate

Vehicle number: SLF1850H
 Make & Model: Lexus IS250
 Chassis number: JTHBK262605086763

Date of survey:
 Name of surveyor:
 Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ 1,759.00
2	Bonnet RH hinge	1	\$ 129.00
3	Bonnet LH hinge	1	\$ 129.00
4	Bonnet lock	1	\$ 235.00
5	Bonnet insulator	1	\$ 218.00
6	Front bumper	1	\$ 881 987.10
7	Front bumper number plate	1	\$ 187.00
8	Front bumper RH fog lamp	1	\$ 329.40
9	Front bumper RH fog lamp cover	1	\$ 89.10
10	Front bumper RH fog lamp side cover	1	\$ 55.30
11	Front bumper LH fog lamp	1	\$ 329.40
12	Front bumper LH fog lamp cover	1	\$ 89.10
13	Front bumper LH fog lamp side cover	1	\$ 55.30
14	Front bumper RH side retainer	1	\$ 68.00
15	Front bumper LH side retainer	1	\$ 68.00
16	Front bumper reinforcement	1	\$ 478.00
17	Front bumper inner sponge	1	\$ 158.90
18	Front bumper lower grille	1	\$ 189.20
19	Front bumper towing cover	1	\$ 31.10
20	Front bumper upper rubber seal	1	\$ 165.60
21	Front grille	1	\$ 602.00
22	Front grille emblem	1	\$ 118.30
23	Front air duct	1	\$ 113.50
24	RH headlamp	1	\$ 2,188.00
25	RH headlamp lower bracket	1	\$ 141.30
26	LH headlamp	1	\$ 2,188.00
27	LH headlamp lower bracket	1	\$ 141.30
28	Front brace panel	1	\$ 92.30
29	Support panel	1	\$ 1,296.50
30	Support panel top cover	1	\$ 304.50
31	Horns	2	\$ 215.70
32	Aircon condenser	1	\$ 1,205.00
33	Radiator assy	1	\$ 1,518.00
34	Radiator fan assy	1	\$ 701 1,309.00
35	Front RH fender	1	\$ 970.00
36	Front RH fender splash shield	1	\$ 278.00
37	Front LH fender	1	\$ 970.00
38	Front LH fender splash shield	1	\$ 278.00
39	Aircon condenser	1	\$ 1,281.60

Air filter - new \$450 ✓

40	Radiator assy	1	\$	1,673.80
41	Radiator fan assy	1	\$	971.60

nn
nn

Parts less 10% \$ 21,589.90 14,462.30
\$ 2,158.99 -10%
\$ 19,430.91 13,016.07

No.	Special Nett Items	Qty	Amount S\$
1	Bonnet insulator clips	1set	\$ 90.00
2	Bonnet sealant	1	\$ 100.00
3	Front grille clips	1set	\$ 60.00
4	Front bumper clips	1set	\$ 80.00
5	Support panel top cover clips	1set	\$ 70.00
6	Front RH fender splash shield clips	1set	\$ 60.00
7	Front LH fender splash shield clips	1set	\$ 60.00
8	Radiator coolant	1	\$ 100.00
9	Front number plate	1	\$ 80.00
		1	\$ 278.00

3 one ✓
nn
20 one ✓
3 one ✓
nn
nn
nn
nn
40

Total: \$ 978.00 120

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,200.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 80.00
5	Remove and replace aircon condenser and pipes to assist repair	\$ 280.00
6	Remove and replace radiator assy and hoses to assist repair	\$ 280.00
7	Refocus and adjust headlamps assy	\$ 100.00
8	Diagnose and reset control unit	\$ 450.00

600
800
40
30
100
100
40
x

Total: \$ 3,670.00 1710

Agreed Amount: (Part by Part / Lump sum)

Tanfiah 97495749 WP 01/11/22 @ 345pm
L/S Repair after repair - To check consistency of accident
tanfiah@lhaauto.com - To check part prices
5 days

Working days: _____

Spare Parts:	\$	19,430.91
Special Nett:	\$	978.00
Labour:	\$	3,670.00

Total Amount:	\$	<u>24,078.91</u>
----------------------	-----------	-------------------------

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SLF1850

Make & Model: Lexus IS250

Chassis number:

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Air filter cover	1	\$ 467.00

\$ 467.00

Parts less 10% \$ 46.70

Total \$ 420.30

No.	Special Nett Items	Qty	Amount S\$

Total: \$ -

No.	Labour and painting	Amount S\$

Total: \$ -

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 420.30

Special Nett: \$ -

Labour: \$ -

14,846.07 + 420.30 = 15,266.37

L/S - 12,213.96

= 12,200.00

Total Amount: \$ 420.30

Taufik 8/11/22.