· · · · · · · · · · · · · · · · · · ·	I 22010726 Dny . SIGNMENT
Tanga same same	
From: Date:	Veh No: SKT 122X Yr Regn: Jan 1 2015
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Audi A3 c.c 1395
at Werkshop m/s	Colour White A/C: Insured / Std / NI / NA
of	Sp.Reading 228951 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: 020225132
Policy No.	C/No: WAUZZZ8V&F1073187
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt-or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 235 55 7219
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or Dan Grady
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. S mm L/Bal. S mn
Est. Repairs: 6 4 days Res.: Yes or No	D.O.A. 25 10 2572 D.O.I. 28 10 2572
Lum Sum: % · 3 Val.: Yes or No	Survey held at CS Ong AMIC
CA / REV / REP. / 24 HRS  Vehicle: IN / Ol	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
Knager Divos SLR 9425	57
10/01/27 hugher 2/5 7,00/- with	· 6 days of in
	35474.40, 84%)
The state of the s	330 ((1)140) 3 ( [3]
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6
1) 10   1   23   : Final Report	Resurvey No. of Trip: \ Survey Fee:
Date/Time, File Return to?	Transportation:
Add F	ee: : Site Insp (\$)s+Rs,si
	: Interview (\$) Photos
Report Format:	: Tech. Invs (\$ ) Others
Lump Sum / I.B.I: (\$ 7000 )	:Weekend (\$)

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	980A
Vehicle No.:	SKT122X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Oct 2022
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI AMBIENTE MY 15
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	CZC225132
Chassis No.:	WAUZZZ8V7F1073187
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$27,195.00
Original Registration Date:	30 Jan 2015
First Registration Date:	30 Jan 2015
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$15,073.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jan 2025
PARF Rebate Amount: Intended COE Rebate Details	\$9,043.00
COE Expiry Date:	29 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,010.00
COE Rebate Amount:	\$14,905.00
Total Rebate Amount:	\$23,948.00

The information contained herein is correct as at 26 Oct 2022

## sgcarmari

Login Sign up

New Cars

**Used Cars** 

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Post an Advertisement Sell it yourself! Advertise it at just

\$68 until it's SOLD!

Post an Ad

Advertiser Login

Make

Ways of Selling

Model



Apex Trading Pte Ltd StarAd



Sort by Date Posted 20 results/page

9 vehicles

Audi A3 SEDAN

Price Depreciation

Reg Date

Any Category

Eng Cap

Veh Type

Advanced Search

Status

Search Selection

Audi A3 SEDAN

Any

Any

2015

Anv

Mileage

Available

Available

Audi A3 Sedan 1,4A TFSI

\$56,800

\$18,310 /yr CF front lip, CF side mirror cover, CF karbel bootlip, CF Karbel rear diffuser. Front 2 wheel bearing hub - Nov 2021, water pump - May 20...

30-Jun-2015

1,395 cc

115,000 km

Luxury

PREMIUM AD

Posted: 18-Sep-2022

Audi A3 Sedan 1.4A TFSI Ambiente

\$55,000

\$15,870 /yr

20-Aug-2015

1,395 cc 103,000 km Luxury

Available

1 Owner. Full Agent Serviced since day One! Pristine condition factory white paintwork. Always parked under sheltered, all wear and tear..

Monster Motors Pte Ltd

Posted: 15-Oct-2022



Audi A3 Sedan 1.4A TFSI **Ambiente** 

\$56,088

\$15,840 /yr

16-Sep-2015

1,395 cc

80,000 km

Available Luxury

Beautifully Done Up Audi A3 1.4 In Amazing Condition With Many Accesories, Brown Leather Upholstery, All Wear And Tear Done Up Wit...

Posted: 17-Oct-2022



Audi A3 Sedan 1.4A TFSI Amhiente

\$56,888

\$15,900 /yr

30-Sep-2015

1,395 cc

71,000 km

Luxury

Available

1 retired owner. 100% accident free unit. Low mileage covered. Timely maintenance and parts change. No expenses spared. Pristine int...

This car comes with 6-mth Sqcarmart Warranty - the best protection for your car. Learn More

Posted: 22-Oct-2022



Y.E.S!! Marbella KR8S PRO Limited Set Promo!

Y.E.S Sale!!! Marbella KR8S PRO 2 Ch Car Camera @ only \$268!!! Limited 10 sets only! T&C Applies

Find out more!



Audi A3 Sedan 1.4A TFSI **Ambiente** 

\$55,900

\$15,290 /yr

19-Oct-2015

1,395 cc

85,600 km

Luxury

Available

Look no further, ideal continental sedan for executives and family car. Beautiful black Audi A3 1.4 TFSI sedan with saddle brown leather...

Posted: 22-Oct-2022



Audi A3 Sedan 1.4A TFSI Ambiente

\$59,888

\$16,460 /yr

30-Oct-2015

1,395 cc

62,911 km

Luxury

Available

CARRO Certified Pre-Owned - All our vehicles undergo a strict 160-point inspection to ensure No Major Accident, and No Mileage Tamper...

Carro

Posted: 07-Oct-2022

Audi A3 Sedan 1.4A TFSI **Ambiente** 

\$56,500 \$14,980 /vr 24-Nov-2015

1,395 cc

91.000 km

Luxury

Available

100% Accident Free! Full Loan Available! Bank or In House Loan is Available, We Provide The Lowest Interest Rate, Loan and High Trade..

Posted: 22-Oct-2022

Audi A3 Sedan 1.4A TFSI S-

\$56,800

\$15,040 /vr

27-Nov-2015

1.395 cc

84.864 km

Luxury

Available

tronic Ambiente

## C. S. ONG AUTO PTE LTD

Co. Reg. No.: 201408916W

7030, ANG MO KIO AVE 5, #B1-01 NORTHSTAR @ AMK, SINGAPORE 569880

TEL: 6484 1933 | FAX: 6481 1916

E-Mail: csongauto.claims@yahoo.com.sg

To:

**BUDGET DIRECT** 

Att:

Motor Claims Dept

ACCIDENT INVOLVING SLR8425T [YOUR INSURED] & SKT122X [OUR CLIENT] ON 25/10/2022.

## **ESTIMATED REPAIR COSTS FOR SKT122X**

MODEL: AUDI A3

<b>QTY</b>	<u>PARTS</u>	<b>AMOUNT</b>
1PC	HEAD LAMP RH Maker 3555-76	\$ 9,892.00
1PC	HEAD LAMP LOWER BRACKET RH	\$ 250.00 ×
1PC	BONNET MH	\$ 3,933.00
1PC	FRONT FENDER RH Dust 763.70	\$ 1,672.00
1PC	FRONT FENDER INNER SHIELD RH tom 117.00	\$ 201.00
1PC	FRONT WHEEL BEARING RH	\$ 395.00 ×
1PC	FRONT WHEEL BEARING HUB RH	\$ 499.00 \( \neq \)
1PC	FRONT KNUCKLE ARM RH	\$ 1,239.00
1PC	FRONT LOWER ARM RH	\$ 785.00 \( \square\$
1PC	FRONT UPPER ARM RH HA	\$ 699.00 ×
1PC	FRONT CONTROL ARM RH 🛰	\$ 592.00 \( \square\)
1PC	FRONT THRUST ARM RH	\$ 782.00
1PC	FRONT ABSORBER RH	\$ 1,164.00
1PC	FRONT STABILIZER LINK RH 4	\$ 359.00 ×
1PC	FRONT STABILIZER BAR	\$ 510.00 \( \
1PC	FRONT TIE ROD RH	\$ 310.00 ×
1PC	FRONT TIE ROD END RH	\$ 882.00 🖈
1PC	STEERING RACK & PINION ASSY	\$ 3,190.00
1PC	DRIVE SHAFT RH	\$ 2,492.00
1PC	FRONT BUMPER and Pull	\$ 2,015.00
1PC	FRONT BUMPER SIDE RETAINER RH	\$ 184.00 \( \square\)
1PC	FRONT BUMPER SPONGE	\$ 629.00
1PC	FRONT BUMPER REINFORCEMENT 44	\$ 839.00
1PC	FRONT BUMPER NOZZLE COVER RH	\$ 203.00
1PC	FRONT BUMPER NOZZLE PUMP RH	\$ 422.00
1PC	FRONT BUMPER FOG LAMP GARNISH RH	\$ 310.00
1PC	FRONT BUMPER FOG LAMP OUTER GARNISH RH	\$ 294.00 >
1PC	WIPER WASHER TANK	\$ 392.00 \(
1PC	WIPER WASHER TANK MOTOR HA	\$ 349.00

PARTS SUM: \$ 38.116  5,557.48  LABOUR & SPECIAL NETT ITEMS  * TO SUPPLY HEAD LAMP CLIPS HALE * TO SUPPLY FRONT BUMPER CLIPS HALE * TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HALE * TO SUPPLY FRONT FENDER CAT STICKER LIMITED EDITION HAP \$ 300 * TO SUPPLY FRONT FENDER KAT STICKER LIMITED EDITION HAP \$ 300 * TO SUPPLY FRONT BUMPER LOWER SKIRTING CAT TO SUPPLY PRONT BUMPER LOWER SKIRTING CAT TO SUPPLY IPC SPORT RIM CAR TO SUPPLY IPC SPORT RIM CAR TO SUPPLY IPC SPORT RIM CAR TO SUPPLY IPC TYRE HALE * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 1.000 * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000 * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000 * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400 * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150 * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120 * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200 * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 3.00 * ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8.170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  28 10 272 8 120000	.00 ×
* TO SUPPLY HEAD LAMP CLIPS HALE * TO SUPPLY FRONT BUMPER CLIPS HALE * TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HALE * TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HALE * TO SUPPLY FRONT FENDER INNER SHIELD CLIPS HALE * TO SUPPLY FRONT BUMPER LOWER SKIRTING COAT TO SUPPLY FRONT BUMPER LOWER SKIRTING COAT TO SUPPLY IPC SPORT RIM (AACTOR) * TO SUPPLY IPC SPORT RIM (AACTOR) * TO SUPPLY IPC TYRE HALE * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS * TO TUFF COAT DAMAGED AREAS * TO TUFF COAT DAMAGED AREAS * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET * ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL:  * S 8,170  * GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): * 5 42,474  * S 8,47 . 48  * 15 NO SUPPLY HEAD AND AND AND AND AND AND AND AND AND A	
* TO SUPPLY HEAD LAMP CLIPS HALE * TO SUPPLY FRONT BUMPER CLIPS HALE * TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HALE * TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HALE * TO SUPPLY FRONT FENDER INNER SHIELD CLIPS HALE * TO SUPPLY FRONT BUMPER LOWER SKIRTING COAT TO SUPPLY FRONT BUMPER LOWER SKIRTING COAT TO SUPPLY IPC SPORT RIM (AACTOR) * TO SUPPLY IPC SPORT RIM (AACTOR) * TO SUPPLY IPC TYRE HALE * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS * TO TUFF COAT DAMAGED AREAS * TO TUFF COAT DAMAGED AREAS * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET * ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL:  * S 8,170  * GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): * 5 42,474  * S 8,47 . 48  * 15 NO SUPPLY HEAD AND AND AND AND AND AND AND AND AND A	
* TO SUPPLY HEAD LAMP CLIPS HAD  * TO SUPPLY FRONT BUMPER CLIPS HAD  * TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS  * TO SUPPLY FRONT FENDER CAT STICKER LIMITED EDITION HE  * TO SUPPLY FRONT FENDER INNER SHIELD CLIPS  * TO SUPPLY FRONT BUMPER LOWER SKIRTING CAT OF SUPPLY FRONT BUMPER LOWER SKIRTING CAT OF SUPPLY IPC SPORT RIM  * TO SUPPLY IPC SPORT RIM  * TO SUPPLY IPC SPORT RIM  * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS  * TO REMOVE & PANEL BEAT ALL DAMAGED AREAS  * TO TUFF COAT DAMAGED AREAS  * TO TUFF COAT DAMAGED AREAS  * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS  * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET  * ALL MEMORIES TO FACTORY DEFAULT SETTINGS  * LABOUR & S/N TOTAL:  * \$ 8.170  * GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST):  * \$ 42.474  * \$ 98 10 272 & 130000  * LIKK Auto Consultants hence the Repairer of the following:  * To desperate polorialities sporp point  * To display denorates (1901 and 180 per 1901)  * Parts priors are subject to confirmed  * To display denorates (1901) and the per 1901 and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorates (1901) and 180 per 1901  * To display denorated (1901) and 180 per 1901  * To display denorated (1901) and 180 per 1901  * To display denorated (1901) and 180 per 1901  * To display denorated (1901) and 180 per 1901  * To display denorated (1901) and 180 per 1901  * To display denorated (1901) and 180 per 1901  * To denorate (1901) and 180 per 1901  * To denorate (1901) and 180 per 1901  * To denorate	.40
* TO SUPPLY FRONT BUMPER CLIPS **  ** TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS **  ** TO SUPPLY FRONT FENDER CAT STICKER LIMITED EDITION **  ** TO SUPPLY FRONT FENDER CAT STICKER LIMITED EDITION **  ** TO SUPPLY FRONT FENDER INNER SHIELD CLIPS **  ** TO SUPPLY FRONT BUMPER LOWER SKIRTING **  ** TO SUPPLY IPC SPORT RIM (**  ** TO SUPPLY IPC SPORT RIM (**  ** TO SUPPLY IPC SPORT RIM (**  ** TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 1,500  ** TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,500  ** TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000  ** TO TUFF COAT DAMAGED AREAS \$ 2,00  ** TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400  ** TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150  ** TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  ** TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 3.00  ** TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 3.00  ** ALL MEMORIES TO FACTORY DEFAULT SETTINGS  ** LABOUR & S/N TOTAL: \$ 8.170  ** GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  ** For resurve belore/after spray peints of the following: ** To resurve belore/after spray peints of the following: ** To deplay damaged and the fill of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirm of the following: ** To deplay damaged and subject to confirms of the following: ** To deplay damaged and subject to confirms of	
* TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS 4.3 \$ 300 * TO SUPPLY FRONT FENDER CAT STICKER LIMITED EDITION 46 \$ 300 * TO SUPPLY FRONT FENDER INNER SHIELD CLIPS 4.0 \$ 500 * TO SUPPLY FRONT BUMPER LOWER SKIRTING 6.4 \$ 1835.00 \$ 1,500 * TO SUPPLY IPC SPORT RIM 6.4 \$ 2,000 * TO SUPPLY IPC SPORT RIM 6.4 \$ 800  * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 1,000 * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000 * TO TUFF COAT DAMAGED AREAS \$ 1,000 * TO TUFF COAT DAMAGED AREAS \$ 2,000 * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400 * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150 * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120 * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 2,000 * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 3.00 * ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170    SALY 2.49   SALY 2.49	.00 7
* TO SUPPLY FRONT FENDER CAT STICKER LIMITED EDITION MF S 300 * TO SUPPLY FRONT FENDER INNER SHIELD CLIPS LOWER STORTS WITH STORTS WITH SUPPLY FRONT BUMPER LOWER SKIRTING CAT TO SUPPLY IPC SPORT RIM CAT TO SUPPLY IPC TYRE HAD S 800  * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS S 1,000 * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS S 1,000 * TO TUFF COAT DAMAGED AREAS S 1,000 * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS S 400 * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS S 150 * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT S 120 * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS S 200 * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET S 3,000 ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: S 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): S 42,474  28 10 200 1 1300 1 14 14 14 14 14 14 14 14 14 14 14 14 1	.00 2
* TO SUPPLY FRONT FENDER INNER SHIELD CLIPS **  ** TO SUPPLY FRONT BUMPER LOWER SKIRTING Coat TO SUPPLY FRONT BUMPER LOWER SKIRTING Coat TO SUPPLY IPC SPORT RIM Coat TO SUPPLY IPC SPORT RIM Coat TO SUPPLY IPC TYRE Had SUPPLY I	.00 ×
* TO SUPPLY FRONT BUMPER LOWER SKIRTING C+ 1835 W \$ 1,500 * TO SUPPLY IPC SPORT RIM C+ 1835 W \$ 2,000 * TO SUPPLY IPC TYRE WHA \$ 800  * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 1,000  * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000  * TO TUFF COAT DAMAGED AREAS \$ 2,000  * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400  * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 3,000  ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  * \$ 30 4 10 200 C 125000 C 10 10 10 10 10 10 10 10 10 10 10 10 10	× 00.
* TO SUPPLY IPC SPORT RIM  * TO SUPPLY IPC TYRE HE SOURCE SENTING SENT	.00 15
* TO SUPPLY IPC TYRE HIM S 800  * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 1,000  * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000  * TO TUFF COAT DAMAGED AREAS \$ 200  * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400  * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 3.00  ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  28 10 272 8 120000  LKK Auto Consultants hence the Repaire of the following: 1 To deplay damaged part(s) during 1 Parts prices are survey a beforea later sorary paint 1 To deplay damaged part(s) during 1 Parts prices are survey as a 1 Without 1 Parts prices are survey as a 1 Parts prices a	.00 8
* TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 1,000  * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000  * TO TUFF COAT DAMAGED AREAS \$ 200  * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400  * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 3.00  ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  * B 10 272 & 13000 \$ 45 44,74  * To display damaged part(s) during 10 for parts prices are subject to confirms 10 for parts prices are subjec	.00 1
* TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 1,000  * TO TUFF COAT DAMAGED AREAS \$ 200  * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400  * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300  ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474   BRITE OF THE REPAIR OF THE REPAIR OF THE REPAIR TO RESURE STOP ADMINISTRATED TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  LKK Auto Consultants hence of the Repairer of the Ollowing:  To display damaged part(s) during in Total Result in Total Part in Total P	.00 🗙
* TO TUFF COAT DAMAGED AREAS \$ 200  * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400  * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300  ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  * BY 10 272 & 1300	.00° J
* TO TUFF COAT DAMAGED AREAS \$ 200  * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400  * TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS \$ 150  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300  ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  * BY 10 272 & 1300	.00 6
* TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET  * ALL MEMORIES TO FACTORY DEFAULT SETTINGS  * LABOUR & S/N TOTAL:  * GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST):  * \$ 42,474  * \$ 400  * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS  * LABOUR & S/N TOTAL:  * \$ 8,170  * GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST):  * \$ 42,474  * \$ 7,000  * LKK Auto Consultants hence of the Repairer of the following:  * To resurvey before/after spray plain  * To display damaged part(s) during of parts prices are subject to confirmate the confirmation of the	. <del>0</del> 0 3 2
* TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120  * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300  ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  88.42.48  15 7,000  LKK Auto Consultants hence of the Repairer of the following:  10 isplay damaged part(s) during of the parts prices are subject to confirmance of the parts prices are	.00 🛏
* TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200.  * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300 ALL MEMORIES TO FACTORY DEFAULT SETTINGS  **  **  **  **  **  **  **  **  **	.00 ►
* TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300 ALL MEMORIES TO FACTORY DEFAULT SETTINGS  LABOUR & S/N TOTAL: \$ 8,170  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474  38 42 49  LKK Auto Consultants hence of the Repairer of the following:  To resurvey before/after spray paint  To display damaged part(s) during of the parts prices are subject to confirmate of the parts prices are subject to confirmate or the parts prices are subject to c	.00
LABOUR & S/N TOTAL: \$ 8,170.  GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474.  28 10 272 8 13000   S 42,474.  15	.00-3
GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,474.  38 10 272 8 13000	.00
28 10 272 € 13000 LKK Auto Consultants hence of the Repairer of the following:  To resurvey before/after spray paint  To display damaged part(s) during of the Parts prices are subject to confirmate	.00
LKK Auto Consultants hence of the Repairer of the following:  To resurvey before/after spray paint  To display damaged part(s) during of the Parts prices are subject to confirmate the Parts prices	40
the Repairer of the following:  To resurvey before/after spray paint  To display damaged part(s) during a  Parts prices are subject to confirma  Third party survey is on a "Without"  No illegal modification(s) is allowed.	
the Repairer of the following:  To resurvey before/after spray paint  To display damaged part(s) during a  Parts prices are subject to confirma  Third party survey is on a "Without"  No illegal modification(s) is allowed.	
the Repairer of the following:  To resurvey before/after spray paint  To display damaged part(s) during a  Parts prices are subject to confirma  Third party survey is on a "Without"  No illegal modification(s) is allowed.	otify
To display damaged part(s) during to Parts prices are subject to confirma Third party survey is on a "Without No illegal modification(s) is allowed a Supplementary item(s) must be res	
Parts prices are subject to confirma  Third party survey is on a "Without  No illegal modification(s) is allowed  Supplementary item(s) must be res	esurvev
Third party survey is on a "Without  No illegal modification(s) is allowed  Supplementary item(s) must be res	tion
Supplementary item(s) must be res	Prejudice
	urveyed a
is subject to final approval from Ins	urance C
Acknowledged by Repairer	
JK(c A. J.) ( ) Signature:	