

ASS. REC. BY: Marcus

REF:

CS/AIS 22010733/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1) orla tyris☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.L. (\$

1/11/22
 2015 model from S&C report
 1/5 \$2900 indmt shown. Cred \$9337.55, 76%)

MER-70

2900

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email: shawn7530@hotmail.com

27 Oct 2022

Vehicle No.: SGD 3005 M

Model: TOYOTA VIOS

Not Authorized
28/10/22
1/5 \$ 2900
3 days

QTY	DESCRIPTION	AMT S\$
	<u>List Items</u>	
1	Front bonnet <i>11</i>	\$ 892.00 X
1	Front bonnet lock <i>11</i>	\$ 131.00 X
1	Front headlamp - RH <i>320</i>	656.30 \$ 1,149.00 /
1	Front grille <i>CNA</i>	221.10 \$ 477.00 /
1	Front grille logo <i>11</i>	75.00 \$ 89.50 /
1	Front bumper <i>Dis</i>	533.90 \$ 586.00 /
1	Front bumper centre grille <i>Tw1/To-1</i>	214.20 \$ 269.00 /
1	Front bumper fog lamp <i>CNA</i>	405.10 \$ 516.00 /
1	Front bumper fog lamp cover <i>Tw1</i>	\$ 135.00 /
1	Front bumper lower moulding <i>11</i>	\$ 130.20 X
1	Front bumper reinforcement <i>R</i>	\$ 399.00 X
1	Front bumper under cover <i>11</i>	\$ 275.20 X
1	Front bumper side retainer <i>o/s CNA</i>	75.50 \$ 98.00 1pc
2	Front bumper chrome mouldings <i>o/s CNA</i>	145.00 \$ 350.00 1pc
1	Front fender - RH <i>o/s</i>	\$ 399.50 X
1	Front fender inner shield <i>o/s</i>	\$ 160.50 /
1	Front fender bracket <i>11</i>	\$ 83.60 X
1	Front support panel <i>R</i>	\$ 1,162.00 X
1	Front support panel top garnish <i>De/Tw1</i>	\$ 285.00 ✓
1	Front brace panel <i>11</i>	\$ 145.00 X
1	Front wiper tank <i>De</i>	184.60 \$ 263.30 /
1	Front wiper motor <i>11</i>	\$ 189.50 X
1	Front wheel hub with bearing <i>11</i>	\$ 355.90 X
1	Front shock absorber <i>11</i>	\$ 360.80 X
1	Front knuckle arm <i>11</i>	\$ 560.50 X
1	Front lower arm <i>11</i>	\$ 300.90 X
		\$ 9,763.40
	Less 25%	\$ 2,440.85
		\$ 7,322.55

Special Nett Items

1	Front bumper clip (1 set)	111	\$	60.00	40
1	Front fender inner shield clip (1 set)	111	\$	45.00	40
1	Front tyre	11	\$	350.00	X
1	Front wheel rim -RH	11	\$	600.00	X
				\$	1,055.00

S/N. Labour Charges

1	To check wiring and reset headlamps focusing.		\$	80.00	20
2	To remove and refit front undercarriage.		\$	111 300.00	X
3	To conduct wheel alignment.		\$	180.00	60
4	To apply undercoating.		\$	111 200.00	X
5	Panel beating.		\$	1,600.00	550
6	To re-spray painting on the affected areas.		\$	1,500.00	600
				\$	3,860.00

Grand Total : \$ 12,237.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3091-20
252
2318-40
80
1230
3628-40
212
29022