

Vehicle Damage Assessment Report for [SJX6414E]

Estimate Created: 19/12/2022 00:30 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 19/12/2022 03:17 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Vios
Engine Type			
License Plate Number	SJX6414E	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$5750.00 with 9 days for repair

Insurlogic 1 (19/12/2022 03:17)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
ROOF PANEL SIDE MOULDING		1	336.00	-25.00 %	252.00
FRONT WINDSCREEN		1	1070.20	-25.00 %	802.65
FRONT WINDSCREEN MOULDING		1	120.00	-25.00 %	90.00
IU BRACKET		1	25.00	-25.00 %	18.75
REAR VIEW MIRROR		1	212.64	-25.00 %	159.48
FRONT WIPER GARNISH RH		1	75.82	-25.00 %	56.87
BONNET		1	821.00	-25.00 %	615.75
HEADLAMP RH		1	543.90	-25.00 %	407.93
FRONT FENDER RH		1	581.40	-25.00 %	436.05
FRONT FENDER EMBLEM VVTI		1	82.60	-25.00 %	61.95
FRONT DOOR RH		1	773.60	-25.00 %	580.20
FRONT DOOR BLACK TAPE		1	97.30	-25.00 %	72.98
WING MIRROR ASSY		1	475.00	-25.00 %	356.25
BOOTLID LOGO		1	95.40	-25.00 %	71.55
VIOS EMBLEM		1	78.20	-25.00 %	58.65
BOOTLID J EMBLEM		1	68.50	-25.00 %	51.38

Parts Subtotal 4,092.44

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT WINDSCREEN PRIMER AND CLAENER		1.0	60.00	0.00 %	60.00
FRONT WINDSCREEN SEALANT		1.0	60.00	0.00 %	60.00
FRONT WINDSCREEN INNER SEAL		1.0	40.00	0.00 %	40.00

Materials Subtotal 160.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	1000.00	0.00 %	1,000.00
CHECK WIRING	RnR	30.00	0.00 %	30.00

RNR FRONT WINDSCREEN	RnR	120.00	0.00 %	120.00
RNR REAR INTERIOR UPHOLSTRY	RnR	100.00	0.00 %	100.00
ANTI RUST	RnR	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	1600.00	0.00 %	1,600.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	1,350.00
			Paint Labor Subtotal	1,600.00
			Labor Subtotal	2,950.00

Summary

Repair Cost	7,202.44
Discount(20 %)	(1,452.42)
	5,750.02
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,750.02