

LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1

#01-384 SINGAPORE 408700

OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002

E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 26-Oct-22

Registration no. : SJX6414E / TOYOTA VIOS J AUTO / 2010

DOA : 25-Oct-22

Estimate No. : LKT006_SJX6414E_VIOS

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Roof panel	870.30 <i>Ry</i>
2	2	Roof panel side moulding x2	512.20 <i>ne</i>
3	1	Roof lining	594.50 <i>x</i>
4	1	Front windscreen	1430.00 <i>an</i>
5	1	Front windscreen pillar RH	0.00 <i>Ry</i>
6	1	Front windscreen pillar inner garnish RH	141.70 <i>x</i>
7	1	Front windscreen pillar LH	0.00 <i>Ry</i>
8	1	Front windscreen moulding	176.45 <i>ne</i>
9	1	IU bracket	25.00 <i>ne</i>
10	1	Rear view mirror	212.64 <i>bro</i>
11	1	Rear windscreen moulding	138.00 <i>x</i>
12	1	Front wiper garnish RH	75.82 <i>cut</i>
13	1	Front wiper garnish LH	75.82 <i>x</i>
14	1	Bonnet	821.00 <i>bt</i>
15	1	Front bumper	745.30 <i>Ry</i>
16	2	Front bumper side retainer x2	248.00 <i>x</i>
17	2	Front bumper bracket x2	141.00 <i>x</i>
18	1	Headlamp RH	680.40 <i>cur</i>
19	1	Front fender RH	674.90 <i>bt</i>
20	1	Front fender emblem 'VVTI' RH	82.60 <i>ne</i>
21	1	Front door RH	773.60 <i>bt</i>
22	1	Front door black tape RH	97.30 <i>ne</i>
23	1	Front door LH	0.00 <i>Ry</i>
24	1	Front door black tape LH	97.30 <i>x</i>
25	1	Wing mirror assy RH	475.00 <i>bro</i>
26	1	Rear door RH	0.00 <i>Ry</i>
27	1	Rear door black tape RH	94.00 <i>a</i>
28	1	Rear fender RH	0.00 <i>Ry</i>
29	1	Bootlid	0.00 <i>Ry</i>
30	1	Bootlid logo	95.40 <i>ne</i>
31	1	Bootlid emblem 'VIOS'	78.20 <i>ne</i>
32	1	Bootlid emblem 'J'	68.50 <i>ne</i>
33	1	Rear bumper	0.00 <i>Ry</i>
34	2	Rear bumper side retainer x2	240.40 <i>x</i>
			9665.33
Less 25%			2416.33
			7249.00

LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1

#01-384 SINGAPORE 408700

OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002

E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 26-Oct-22

Registration no. : SJX6414E / TOYOTA VIOS J AUTO / 2010

DOA : 25-Oct-22 Estimate No. : LKT006_SJX6414E_VIOS

S/N	Qty	Item	Amount
<u>SPECIAL NETT ITEMS</u>			
1	1	Sundries	60.00 X
2	1set	Front bumper clips	80.00 X
3	1set	Rear bumper clips	80.00 X
4	1	Front door inner seal RH	100.00 X
5	1set	Front door trimboard clips RH	65.00 X
6	1	Front door inner seal LH	100.00 X
7	1set	Front door trimboard clips LH	65.00 X
8	1	Rear door inner seal RH	100.00 X
9	1set	Rear door trimboard clips RH	60.00 X
10	1	Rear fender inner trim clips RH	70.00 X
11	1	Front windscreen primer & cleaner	100.00 rel 60
12	1	Front windscreen sealant	80.00 rel 60
13	1	Front windscreen inner seal	60.00 rel 40
14	1	Rear windscreen primer & cleaner	100.00 X
15	1	Rear windscreen sealant	80.00 X
16	1	Rear windscreen inner seal	60.00 X
Parts Total			1260.00
			8509.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<u>LABOUR & MISC CHARGES</u>			
1	1	Panel beating and strengthen parts on accident area.	1750.00 1000
2	1	Check wiring system after disconnect and connect.	80.00 30
3	1	To R&R front windscreen for replacement parts.	150.00 120
4	1	To R&R rear windscreen for replacement parts.	150.00 X
5	1	To R&R interior upholstery for replacement parts.	200.00 100
6	1	To apply undercoating for rust roofing.	200.00 12.89 100
7	1	Spray painting on accident area.	2400.00 1600
Labour Total			4930.00
Total Parts and Labour Cost of Repair			13439.00

20% Lump sum

COR (L/S)

Pre-Repair Survey :-

Name :



Taufik 97495749 / 62563561

Not Authorise 09 days

28/10/22 @ 5pm

Ex: to be advise

Lumpsum, Resurvey after repair

taufik@lkhauto.com

Page 2 of 4