

LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1

#01-384 SINGAPORE 408700

OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002

E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 26-Oct-22

Registration no. : SJX6414E / TOYOTA VIOS J AUTO / 2010

DOA : 25-Oct-22

Estmate No. : LKT006_SJX6414E_VIOS

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Roof panel	870.30	Ry
2	2	Roof panel side moulding x2 <i>2468</i>	336 512.20	nee
3	1	Roof lining	594.50	X un
4	1	Front windscreen	1070.20 1430.00	un
5	1	Front windscreen pillar RH	To Repair 0.00	Ry
6	1	Front windscreen pillar inner garnish RH	141.70	X un
7	1	Front windscreen pillar LH	To Repair 0.00	Ry
8	1	Front windscreen moulding	120 176.45	nee
9	1	IU bracket	25.00	nee
10	1	Rear view mirror	212.64	bro
11	1	Rear windscreen moulding	138.00	X un
12	1	Front wiper garnish RH	75.82	cut
13	1	Front wiper garnish LH	75.82	X un
14	1	Bonnet	821.00	bt
15	1	Front bumper	745.30	Ry
16	2	Front bumper side retainer x2	248.00	X un
17	2	Front bumper bracket x2	141.00	X un
18	1	Headlamp RH	543.90 680.40	nee
19	1	Front fender RH	581.40 674.90	bt
20	1	Front fender emblem 'VVTI' RH	82.60	nee
21	1	Front door RH	773.60	bt
22	1	Front door black tape RH	97.30	nee
23	1	Front door LH	To Repair 0.00	Ry
24	1	Front door black tape LH	97.30	X un
25	1	Wing mirror assy RH	475.00	bro
26	1	Rear door RH	To Repair 0.00	Ry
27	1	Rear door black tape RH	94.00	X un
28	1	Rear fender RH	To Repair 0.00	Ry
29	1	Bootlid	To Repair 0.00	Ry
30	1	Bootlid logo	95.40	nee
31	1	Bootlid emblem 'VIOS'	78.20	nee
32	1	Bootlid emblem 'J'	68.50	nee
33	1	Rear bumper	To Repair 0.00	Ry
34	2	Rear bumper side retainer x2	240.40	X un
			9665.33	5456.56
				4092.42
			2416.33	
			7249.00	

Less 25%

LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1

#01-384 SINGAPORE 408700

OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002

E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 26-Oct-22

Registration no. : SJX6414E / TOYOTA VIOS J AUTO / 2010

DOA : 25-Oct-22

Estmate No. : LKT006_SJX6414E_VIOS

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries	60.00	X
2	1set	Front bumper clips	80.00	X
3	1set	Rear bumper clips	80.00	X
4	1	Front door inner seal RH	100.00	X
5	1set	Front door trimboard clips RH	65.00	X
6	1	Front door inner seal LH	100.00	X
7	1set	Front door trimboard clips LH	65.00	X
8	1	Rear door inner seal RH	100.00	X
9	1set	Rear door trimboard clips RH	60.00	X
10	1	Rear fender inner trim clips RH	70.00	X
11	1	Front windscreen primer & cleaner	100.00	rel - 60
12	1	Front windscreen sealant	80.00	rel - 60
13	1	Front windscreen inner seal	60.00	rel - 40
14	1	Rear windscreen primer & cleaner	100.00	X 7 X
15	1	Rear windscreen sealant	80.00	X 7 X
16	1	Rear windscreen inner seal	60.00	X
Parts Total			1260.00	160
			8509.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	4092.42	1750.00	1000
2	1	Check wiring system after disconnect and connect.	160	80.00	30
3	1	To R&R front windscreen for replacement parts.	2950	150.00	120
4	1	To R&R rear windscreen for replacement parts.	7202.42	150.00	X 40
5	1	To R&R interior upholstery for replacement parts.	415 \$ 5750	200.00	100
6	1	To apply undercoating for rust roofing.	29 days	200.00	100
7	1	Spray painting on accident area.		2400.00	1600
Labour Total				4930.00	2950

Total Parts and Labour Cost of Repair

13439.00

20% Lump sum

COR (L/S)

Pre-Repair Survey :-

Name :



Taufik 97495749/62563561

Not Authorise 09 days

28/10/22 @ 5pm

Ex: to be advise

Lumpsum, Resurvey after repair

taufik@lkhauto.com

Page 2 of 4