

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

Trusty Cars Pte Ltd
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TP Sampo
Hiki Kary

31st OCT 2022

Accident date: 27th OCT 2022

Estimated repair cost for vehicle no: SNC2661Y VOLVO V60

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid B5C logo		\$95.00 +
2	1	Rear tail lamp-RH		\$855.00 +
3	1	Rear Bumper		\$1,772.00 +
	1	Rear Bumper Side Reflector-RH		\$95.00 +
4	2	Rear Bumper Side Bracket	\$112.00	\$224.00 +
5	1	Rear Bumper reverse sensor-SET		\$600.00 +
6	1	Rear bumper lower cover		\$655.00 +
7	8	Rear bumper clips	\$8.50	\$68.00 +
8	1	rear fender -RH Distorted		\$1,450.00 ✓
9	1	Rear fender inner trim board-RH New		\$655.00 +
10	1	rear fender inner panel -RH New		\$955.00 +
11	1	rear fender R/H garnish cut		\$255.00 ✓
12	10	rear fender R/H garnish clips New	\$5.00	\$50.00 20
13	1	Rear door-RH Distorted		\$2,150.00 ✓
14	1	Rear door top hinges-RH New		\$174.00 +
15	1	Rear door lower hinges-RH New		\$185.00 +
16	1	Rear door top moulding-RH New		\$255.00 +
17	1	Rear R/H side skirt cut		\$625.00 ✓
18	1	Rear R/H door inner rubber New		\$285.00 ✓
19	1	Rear R/H door inner trim board Deland		\$955.00 825
20	1	Rear R/H door inner gear motor assy New		\$655.00 425
21	1	Rear R/H door outer handle New		\$155.00 +
22	1	Rear R/H door inner lock New		\$355.00 +
23	1	Rear lower arm-RH New		\$535.00 +
24	1	Rear Knuckle arm-RH New		\$1,450.00 +
25	1	Rear Knuckle arm bearing-RH New		\$312.00 +
26	1	Rear shock absorber -RH New		\$855.00 +
27	1	Rear driver shaft New		\$2,550.00 +
28	1	Rear tyre -RH Punctured		\$450.00 250/5N)
29	1	Rear rim- RH nn		\$600.00 X

Subtotal :- \$20,275.00

6035 S.N: 250
5431.50

Labour charges

To remove & re-fix cushion	\$120.00 80
To remove & re-fix reverse sensor	\$100.00 50
To remove & re-fix rear exhaust	\$0.00 +
Wheel alignment (computer)	\$120.00 80
To remove & re-fix petrol tank	\$180.00 80
to remove & Refix rear undercarriage -RH	\$200.00 150
To Remove & Refix rear door -RH <i>litup</i>	\$180.00 80
Towing charges	\$150.00 120
To Check Wiring System	\$80.00 30
Tuff Kote	\$150.00 60
Panel beating	\$1,000.00 800
Spray painting	\$1,000.00 600

Subtotal :- \$3,280.00

Total:- \$23,555.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
L/S 0704p

blnd: 7811.50

L/S: 6.2K