



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22010739/Gqy3e2 Date: 05/01/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKA 6793U	Veh. Inspected	SJG 7627R
Policy No.		Coverage (\$)	0.00
Claim No.	C10018211/JT	Excess (\$)	0.00
Assign From	SALIZAWATI HAIZAR	Assign Date	28/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALLION 1.8	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ZRT2603032515	Colour	BLACK
Odometer	455001 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/10/2022	Inspection Date	31/10/2022
Survey held at	REVO PERFORMANCE NO 1 KAKI BUKIT AVENUE 6 #02-51 AUTOBAY @KAKI BUKIT SINGAPORE 417883.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	