



REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51 & 53
SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)
TEL : +65 6745 6706 FAX : +65 64843653
EMAIL : contact@revoperformance.com.sg
WEBSITE : www.revoperformance.com.sg
GST REG NO : 201200256H

M/S : Budget Direct Insurance Pte. Ltd.
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
Singapore 239924
TEL : 62212199
ATTN : Motor Claim Department
Your Ref No : C10018211/JT
Claim Type : Third Party
Accident Date : 22/10/2022
TP Veh Reg No : SKA 6793 U

Date : 31 October 2022
Policy No : 5094613309-05
Veh Reg No : SJG 7627 R
Make / : TOYOTA /
Model : ALLION 1.8 A
Chassis No : ZRT2603032515
Engine No : 2ZR0227694
Reg Date : 02/06/2008

ESTIMATE REPAIR COST TO VEHICLE NO : SJG 7627 R

NO	DESCRIPTION	U/PRICE	QUANTITY	LIST PRICE	AMOUNT
1	Rear boot / Blue	\$ 895.00	1	\$ 895.00	
2	Rear boot lock / Cut	\$ 375.00	1	\$ 375.00	
3	Rear boot rubber / Two	\$ 275.00	1	\$ 275.00	
4	Rear boot lock catch X NN	\$ 35.00	1	\$ 35.00	
5	Rear boot hinges / BT	\$ 95.00	12	\$ 190.00	
6	Rear boot emblem (Allion)	\$ 45.00	1	\$ 45.00	
7	Rear boot emblem (A18)	\$ 60.00	1	\$ 60.00	
8	Rear boot center logo	\$ 95.00	1	\$ 95.00	
9	Rear boot center moulding ?	\$ 315.00	1	\$ 315.00	
10	Rear boot center moulding clipse ?	\$ 5.80	2	\$ 11.60	
11	Rear fender LH X Repair	\$ 886.00	1	\$ 886.00	
12	Rear fender inner side garnish X CBA	\$ 586.20	12	\$ 1,172.40	
13	Rear fender inner side garnish clips ?	\$ 5.80	8	\$ 46.40	
14	Rear spare tyre panel X Repair	\$ 896.00	1	\$ 896.00	
15	Rear spare tyre top cover board / el	\$ 565.00	1	\$ 565.00	
16	Rear tool tray (sponge) X NN	\$ 388.00	1	\$ 388.00	
17	Rear fender dust cover X	\$ 98.00	2	\$ 196.00	
18	Rear fender dust cover clipse X / NN	\$ 5.50	4	\$ 22.00	
19	Rear fender air duct LH X	\$ 65.00	1	\$ 65.00	
20	Rear tail lamp / CBA	\$ 585.00	2	\$ 1,170.00	
21	Rear tail lamp panel LH X Repair / Blue	\$ 150.00	1	\$ 150.00	
22	Rear tail lamp clipse X	\$ 12.20	2	\$ 24.40	
23	Rear tail lamp gasket seal X / NN	\$ 38.00	2	\$ 76.00	
24	Rear end panel / Blue	\$ 608.00	1	\$ 608.00	
25	Rear end panel top garnish / DR	\$ 227.00	1	\$ 227.00	

[illegible]



REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51 & 53
SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)
TEL : +65 6745 6706 FAX : +65 64843653
EMAIL : contact@revoperformance.com.sg
WEBSITE : www.revoperformance.com.sg
GST REG NO : 201200256H

M/S : **Budget Direct Insurance Pte. Ltd.**
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
Singapore 239924
TEL : **62212199**
ATTN : **Motor Claim Department**
Your Ref No : **C10018211/JT**
Claim Type : **Third Party**
Accident Date : **22/10/2022**
TP Veh Reg No : **SKA 6793 U**

Date : **31 October 2022**
Policy No : **5094613309-05**
Veh Reg No : **SJG 7627 R**
Make / : **TOYOTA /**
Model : **ALLION 1.8 A**
Chassis No : **ZRT2603032515**
Engine No : **2ZR0227694**
Reg Date : **02/06/2008**

ESTIMATE REPAIR COST TO VEHICLE NO : SJG 7627 R

NO	DESCRIPTION	U/PRICE	QUANTITY	LIST PRICE	AMOUNT
	Labour				
39	Panel beating	\$ 1,800.00	1	\$ 1,800.00	800
40	Check wiring	\$ 60.00	1	\$ 60.00	30
41	Rust proofing	\$ 60.00	1	\$ 60.00	/
42	To remove and refit rear windscreen	\$ 160.00	1	\$ 160.00	X
43	To remove and refit rear seat and up-hole strep	\$ 160.00	1	\$ 160.00	60
44	To remove and replace bumper sensor	\$ 80.00	1	\$ 80.00	40
45	To spray painting	\$ 1,000.00	1	\$ 1,000.00	800
				\$ 3,320.00	\$ 3,320.00
	TOTAL				\$ 11,834.05

TOTAL : SINGAPORE DOLLARS ELEVEN THOUSAND EIGHT HUNDRED THIRTY FOUR AND CENTS FIVE ONLY.

6 Days.
L/S
After repn photo.
Gao Riff Joss 0282
31/10/22.

AUTHORISED SIGNATURE hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party settlement on a "Without Prejudice" basis
- No illegal work is allowed
- Supplier must be resurveyed and is subject to the insurance Company

Acknowledged by Repairer
Signature:
Date: