

ASS. REC. BY:

REF:

C72/ 22010740/Kp

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ Alan's

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMG 2833J Yr Regn: 12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Honda Shuttle c.c. 1496Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 72168 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 8 1203173Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/45 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pettas

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 26/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/11 @ 4759.92 Cash

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06683

Vehicle Insured : GBF1638Z

Accident Date : 26-Oct-2022

Date : 27-Oct-2022

Our Ref : 022175 (CHINA) / CHAN

PAGE : 1

ORE YI PENG (HU YIPENG)

BLK 677C PUNGGOL DRIVE

#13-772

Singapore 823677

Not Authorised

84759.92

Resurvey After Painting

4 days

ESTIMATED COST OF REPAIR FOR HONDA SHUTTLE SMG2833J

1 pc	Tail gate		1,193.40	✓
1 pc	Tail gate outer chrome		383.00	x
2 pcs	Tail gate lamp	<i>N/S</i> @ S\$340.80	681.60	✓
1 pc	Tail gate inner lock		256.00	✓
1 pc	Tail gate rubber		168.00	x
1 pc	Tail gate "SHUTTLE" emblem		55.00	✓
2 pcs	Tail gate glass side moulding	@ S\$ 56.50	113.00	✓
1 pc	Tail gate glass lower moulding		86.20	✓
1 pc	Tail gate inner trim cover		220.00	x
1 pc	Tail gate open pocket		25.00	x
2 pcs	Taillamp	<i>N/S</i> @ S\$520.50	1,041.00	✓
1 pc	Rear end panel		458.20	x
1 pc	End panel top garnish		155.50	x
1 pc	Tools compartment tray	<i>985.00</i>	165.00	x
1 pc	Rear bumper fascia		1,150.40	✓
2 pcs	Rear bumper side retainer	@ S\$ 23.50	47.00	x
2 pcs	Rear bumper reflector sponge	@ S\$ 38.70	77.40	x
1 pc	Rear bumper tow cover		22.50	x
			6,298.20	
Less 20% :			1,259.64	

- | | | | | |
|------|--------------------------------|--|----------|------|
| 1 pc | Rear bumper lower spoiler | | 5,038.56 | ✓ |
| 1 pc | Rear bumper reverse sensor(set | | 400.00 | sn ✓ |
| 1 pc | Rear w/s glass sealant | | 300.00 | sn ? |
| 1 pc | Rear no.plate with box | | 60.00 | sn |
| 1 pc | Rear reverse camera | | 50.00 | sn x |
| | | | 300.00 | sn x |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBF1638Z

Page : 2

To remove & refix rear windscreen
glass and conduct water leak test.

120/ 150.00

To remove roof lining, front and
rear seats, trim board and carpet

120.00 60/

To apply undersealing

nn 60.00 7

To putty and spray replaced parts

900.00 600/

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 500/

Total : S\$ 8,178.56

=====

Singapore Dollars Eight Thousand One Hundred
and Seventy Eight and Cents Fifty Six Only