



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22004616/Dqy3e2-1 Date: 03/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 957B	Veh. Inspected	SLM 166U	
Policy No.	DMHCSNA00006262101	Coverage (\$)	0.00	
Claim No.	SNM22D203350/C02	Excess (\$)	0.00	
Assign From	JACQUELINE TAN	Assign Date	28/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180 AMG	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD1173422N150978	Colour	BLACK	
Odometer	107546 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	FALKEN	6 mm	
L/H Front Tyre	225/40 R18	FALKEN	6 mm	
R/H Rear Tyre	225/40 R18	FALKEN	6 mm	
L/H Rear Tyre	225/40 R18	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/05/2022	Inspection Date	18/05/2022	
Survey held at	MHL AUTOMOBILE SERVICES BLK 3006, UBI ROAD 1 #01-360 SINGAPORE 408700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	