



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/CTI22004616/Dqy3-1	
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Ref: <del>CS3/CTI22004616/Dqy3-1</del>	Date: <del>18/05/2022</del> 28/10/2022
		Code: CTI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SLD 957B	Veh. Inspected	SLM 166U
Policy No.	DMHCSNA00006262101	Coverage (\$)	0.00
Claim No.	SNM22D203350/C02/SLD957B/ TANCHC	Excess (\$)	0.00
Assign From	ADELINE CHNG	Assign Date	<del>18/05/2022</del> 28/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	13/05/2022	Inspection Date	18/05/2022
Survey held at	MHL AUTOMOBILE SERVICES BLK 3006, UBI ROAD 1 #01-360 SINGAPORE 408700		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			