



L.B.S. AUTO CONSULTANTS PTE LTD

Co. Reg. No.: 200311321D

Serangoon Garden Post Office PO Box 398

Singapore 915530

Telephone: 65-62832866 Facsimile: 65-62832166

AUTOMOBILE INSPECTION REPORT

THIAN SUNG CONSTRUCTION PTE LTD
C/O KIAN TEONG AUTO CENTRE
BLOCK 176 SIN MING DRIVE
#01-08 SIN MING AUTOCARE
SINGAPORE 575721

OUR REFERENCE: LBS/MISC/22/08/2189/KTA

REFERENCE: THIRD PARTY CLAIM

VEHICLE NUMBER : **SLZ 9289X** ACCIDENT DATE : 20.08.2022

PARTICULARS OF DAMAGED VEHICLE:

MAKE : NISSAN NOTE 1.2 CVT MODEL : 2018
COLOUR : SILVER MILEAGE KM : 46154
ENGINE CAPACITY : 1198CC V.I.N. : JN1TAAE12Z0980450

STATIC CHECKS: GENERAL CONDITION: GOOD

STEERING: SERVICEABLE BRAKES: SERVICEABLE

TYRE CONDITIONS: SIZE: **185/65R15**

FRONT N/S : 50% FRONT O/S : 50%
REAR N/S : 50% REAR O/S : 50%

Percentages denote the remaining estimated life of the tyre threads

INSPECTION DETAILS AND ADJUSTMENTS: KINDLY SEE SCHEDULE/S OVERLEAF

ORIGINAL QUOTATION: \$ 8,613.00
REVISED QUOTATION: \$ 3,750.00

ESTIMATED NORMAL PERIOD FOR REPAIR: 05 WORKING DAYS ✓

POINT OF IMPACT/S

The impact was confined to the offside broadside portion of the vehicle.

REMARKS

Nil

Damaged Automobile Appraisal
Traffic Accident Investigation and Reconstruction
A.D.R.: Mediation, Conciliation and Arbitration

L.B.S. AUTO CONSULTANTS PTE LTD

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

WORKSHOP:

KIAN TEONG AUTO CENTRE
BLOCK 176 SIN MING DRIVE
#01-08 SIN MING AUTOCARE
SINGAPORE 57521

OUR REFERENCE: LBS/MISC/22/08/2189/KTA

QTY DESCRIPTIONS

VEHICLE NUMBER: SLZ 9289X

- 1 Front bumper
1 Front rh fender
1 Front rh door
1 Front rh door chrome handle
1 Front rh door chrome handle key cover
1 Front rh door side mirror unit
1 Front rh door side mirror cover
1 Front rh door side mirror signal light
1 Front rh door side mirror lower cover
1 Rear rh door

CONDITION ORIGINAL REVISED QUOTATION QUOTATION

Repair	\$ 1,105.00	\$ -
Repair	\$ 695.00	\$ -
Distorted	\$ 995.00	\$ 995.00
Cut	\$ 225.00	\$ 225.00
Cut	\$ 145.00	\$ 145.00
Missing	\$ 495.00	\$ 495.00
Missing	\$ 210.00	\$ 210.00
Missing	\$ 225.00	\$ 225.00
Missing	\$ 118.00	\$ 118.00
Distorted	\$ 980.00	\$ 980.00
	\$ 5,193.00	\$ 3,393.00
Less 10%	\$ -	\$ 339.30
	\$ 5,193.00	\$ 3,053.70

To putty apply primer & spray paint the affected areas. To

spray paint all damaged parts.

To knock & repair all damaged parts, to remove & change all damaged parts.

To remove & refit front rh & rear rh power window to facilitate repair.

To check & repair all electrical wiring.

We are recommending a lump sum repair cost of \$3,750.00 for the entire damage.

This inspection is conducted on a "Without Prejudice" basis.

INSTRUCTION RECEIVED:

FROM: Messrs Kian Teong Auto Centre

ON: 29.08.2022

DATE OF INSPECTION: 29.08.2022

DATE OF REPORT: 14.09.2022

L.B.S. AUTO CONSULTANTS PTE LTD

Mohd Fadhliah Bln Osman
Automotive Appraiser