



24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Fluid Mechanics
C/o: Boost Automotive Pte Ltd
6 Yishun Ind St 1
#05-20 North View Bizhub, Singapore 768090

Date : 13 September 2022
Our ref : BAPT/07/2201/TP

Accident Date : 18 July 2022
Inspection Date : 20 July 2022
Repairer Name : Boost Automotive Pte Ltd
6 Yishun Ind St 1
#05-20 North View Bizhub, Singapore 768090

Type of Survey : Third Party

PARTICULARS OF VEHICLE

| | | | |
|-----------------|---------------------|-----------------|------------------|
| Registration No | : GBH 9503 R | Year / Capacity | : 2018 / 1598 cc |
| Make / Model | : Opel Vivaro | Colour | : Black |
| Chassis No | : W0VF7G606JV601901 | Mileage | : 53735 |
| Engine No | : R9MH413C094458 | | |

CONDITION OF TYRES

| | Make | Size | Thread Balance | Rim |
|----------------|--------------|------------|----------------|--------|
| Front Nearside | : Grenlander | 205/65 R16 | 5 mm | Normal |
| Front Offside | : Grenlander | 205/65 R16 | 5 mm | Normal |
| Rear Nearside | : Grenlander | 205/65 R16 | 5 mm | Normal |
| Rear Offside | : Grenlander | 205/65 R16 | 5 mm | Normal |

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear and front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **215** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$40,900.00** on a contractual basis.

Under normal circumstances, the repair period would be about 32 (Thirty-Two) working days.