

REC BY: Tau

REF: CE4/LPC22010742/TP93

ASSIGNMENT

From: _____ Date: _____
Estimated test: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 865K
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S
	X

Veh No: SLP8060Y Yr Regn: 2017, June
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Prius C C.C. 1497
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 146302 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: STDKD3B3001597702
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 185/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
TOYO / YOKO, etc. Triangle
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.L. 28/10/22
Survey held at Hui Hway Hong Bn.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
Date/Time, File Return to? ☐ : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$)
☐ : Tech's fees (\$)

Survey Fee: _____
Transportation: _____
S + RS \$ _____
Photos _____
Others _____

Redeemed Form: _____
Lump Sum / L.B.H. (\$): _____

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhhib@gmail.com

M/s Popular Rent A Car Pte Ltd
501 Guillemard Road
Singapore 399840

Date of survey: 28 October 2022
Motor Surveyor: LKK Auto Consultants Pte Ltd
Surveyor: Taufik

26th October 2022

Type of repair: **Lump Sum**

Estimate cost of repairs to Toyota Prius C - SLP 8060 Y

1 pc	Tailgate	\$ 930.00	bt ✓
1 pc	Tailgate lock	\$ 396.00	X nn
1 pc	Tailgate trim board	\$ 336.00	X nn
1 pc	Tailgate weatherstrip	\$ 325.00	twi ✓ 298.50
1 pc	Tailgate 'T' emblem	\$ 80.00	nei ✓ 40
1 pc	Tailgate 'Toyota' emblem	\$ 88.00	nn ✓ 63
1 pc	Tailgate 'Prius C' emblem	\$ 88.00	nn ✓ 65
1 pc	Tailgate 'Hybrid' emblem	\$ 88.00	nn ✓ 71
1 pc	Rear bumper	\$ 498.00	de ✓
1 pc	Rear bumper upper retainers RH	\$ 75.00	ora ✓
1 pc	Rear bumper side retainers RH	\$ 85.00	de ✓
1 pc	Rear bumper reinforcement	\$ 636.00	bt ✓ 333.50
1 pc	Rear bumper reinforcement beam RH <i>bracket</i>	\$ 112.00	bt ✓
1 pc	Rear end panel	\$ 580.00	bt ✓
1 pc	Rear end panel garnish	\$ 188.00	de ✓
1 pc	Rear end floor panel	\$ 450.00	Rx ✓
1 pc	Rear end floor panel board	\$ 574.00	X nn
1 pc	Rear end floor panel box deck RH	\$ 262.00	X nn
1 pc	Rear end side trim panel RH	\$ 385.00	de ✓
1 pc	Rear fender RH	\$ 1,552.00	Rx ✓
1 pc	Rear fender inner shield RH	\$ 138.20	twi ✓
1 pc	Rear exhaust silencer baffle plate	\$ 232.00	X nn
1 pc	Taillamp RH	\$ 514.00	cut ✓
1 pc	Taillamp panel RH	\$ 126.00	Rx ✓
1 pc	Taillamp bracket RH	\$ 80.00	ora ✓ 53.80
Less 25%		\$ 8,818.20	
		\$ 2,204.55	1 4430
		\$ 6,613.65	9 3322.50

1 set	Tailgate trim board clips	\$ 30.00	SN <i>kw</i>
1 set	Rear end side trim panel RH clips	\$ 30.00	SN ✓
1 set	Rear bumper clips	\$ 30.00	SN ✓
1 set	Rear RH fender inner shield RH clips	\$ 30.00	SN <i>Lower</i> ✓
1 set	Reverse sensors	\$ 250.00	SN <i>Lower</i> ✓
1 pc	Windscreen sealant	\$ 60.00	SN ✓
	To remove, refix tailgate windscreen glass.	\$ 120.00	✓
	To remove, transfer & refix tailgate fittings.	\$ 80.00	<i>60</i>
	To remove, refix reverse camera	\$ 80.00	<i>30</i>
	To remove & renew reverse sensors	\$ 80.00	<i>30</i>
	To remove & repair rear exhaust silencer & centre pipe	\$ 150.00	<i>kw</i>
	To remove and refix damaged parts, align & renew replaced parts	\$ 1,200.00	<i>800</i>
	Tuff kote	\$ 120.00	<i>30</i>
	Wiring charges	\$ 50.00	<i>30</i>
	Spray painting	\$ 1,200.00	<i>900</i>
		<u>\$ 10,123.65</u>	

2340

Dollars : Ten thousand one hundred twenty-three dollars and sixty-five cents.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3322.50

2340

5662.50

4544.500

7 days