

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | | 00/196K GS1 Reg. No | | | |
|------------|---|--|------------------------|----------|-----------------------|------------------------|
| | | Affiliated to Federation Interna | tionale Des Experts Er | n Automo | bile CS3/ | CTI22002400 |
| | CHINA TAIPING IN | SURANCE (S) PTE LTD | | Ref: | CCS/CTI220 | 02400/Ct y3 |
| | 3 ANSON ROAD # SPRINGLEAF TOV | 16-00 WERSINGAPORE 079909 | | Date: | 15/00/2022 | 27/10/2022 |
| | | | | Code: | | |
| - | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | YQ 134L | Veh. Inspected | <u></u> | SLJ 1362D | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | SNM22D201759/C02 | Excess (\$) | | 0.00 | |
| | Assign From | PAULINE THAM | Assign Date | | 15/03/2022 | 27/10/202 |
| : - | | Vehicle Par | rticulars & Condit | ion | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | - | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| | | | litions of Tyres | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| | | Descrip | otion of Damages | | | |
| | | | | | | |
| - | 1 | | ral Information | | | |
| | Accident Date | 14/03/2022 | Inspection Dat | te | 15/03/2022 | |
| | Survey held at | A-TEC AUTOMOTIVE PTE LT | ΓD | | | |
| | | 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875 | | | | |
| Ба. | Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | |