



A-Tec Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-20 Premier Singapore 415875

Company Reg No: 201227298M

GST Reg No: 201227298M

EMAIL : atec_automotive@yahoo.com.sg

TEL: 6384-5206

FAX: 6384-5205

NAME: Stark Holdings Inn bike Leasing Pte Ltd

DATE : 03-08-22

PROFORMA TAX INVOICE 7291113

JOB NO .

ADDRESS: 149 Shun Li Industrial Park

VEHICLE NO.

SLJ1362D

Kaki Bukit Avenue 1

MAKE&MODEL :

Honda Shuttle

Singapore 416009

TERM

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
1	Lump Sum Repair As Per Surveyor Report			\$ 20,300.00
		SUB-TOTAL		\$ 20,300.00
		ADD GST 7%		\$ 1,421.00
		TOTAL AMOUNT		\$ 21,721.00

IMPORTANT

Please remit payment within 7 days from the due date

*All cheques must be made payable to **A-TEC AUTOMOTIVE PTE LTD***

This a computer generated document.No signature is required.



STARK BIKE & CAR RENTALS

ROC:53433813E

149 SHUN LI INDUSTRIAL PARK KAKI BUKIT AVENUE 1

S416009

HP NO:922011069

DATE:25 MARCH 2022

INVOICE NO:S-LJ1362D

MAKE/MODEL:SHUTTLE

VEHICLE NO:SJ1362D

BILL TO:A-TEC AUTOMOBILE PTE LTD

8 KAKI BUKIT AVENUE 4 #04-20

PREMIER SINGAPORE 415875

ATTN TO:MELVIN

DESCRIPTION:

RENTAL FOR VEHICLE NO:SJ1362D

REPLACE WITH SLG266X

14/03-25/03

12DAYS X
\$150

\$1,800.00

SUB TOTAL:

\$1,800.00

TOTAL AMOUNT:

\$1,800.00



AUTHORISED SIGNATURE

THANK YOU FOR YOUR BUSINESS

IF YOU HAVE ANY QUESTIONS ABOUT THIS INVOICE,PLEASE CONTACT
STARK BIKE & CAR RENTALS

J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08
ONN WAH BUILDING Singapore 486154
Company Reg No: 202125502E
Tel: 6214-0474 Fax: 6384-5205

INVOICE

STARK HOLDINGS INN BIKE LEASING PTE LTD

Invoice No. : JM/220047

C/o: A-Tec Automotive Pte Ltd

Our ref : ATEC/08/0004/JM

8 Kaki Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

Date : 3 August 2022

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES: <ul style="list-style-type: none">• Survey Inspection For Vehicle No. <u>SLJ 1362 D</u>• Digital Photographs Services (Inclusive of storage and submission of digital photographs)• Transportation	
GRAND TOTAL	S\$912.00

E & O. E

All cheque payment should be "Crossed" and make payable to " J&M CONSULTANCY PTE LTD "


J&M Consultancy Pte Ltd



J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08
ONN WAH BUILDING Singapore 486154
Company Reg No: 202125502E
Tel: 6214-0474 Fax: 6384-5205

VEHICLE INSPECTION REPORT

To: STARK HOLDINGS INN BIKE LEASING PTE LTD

Date : 3 August 2022

C/o: A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Our ref : ATEC/08/0004/JM

Accident Date : 14 March 2022

Type of Survey : Third party

Inspection Date : 14 March 2022

Repairer Name : A-Tec Automotive Pte Ltd

8 Kaki Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

PARTICULARS OF VEHICLE

Registration No : SLJ 1362 D

Year / Capacity : 2016 / 1496 cc

Make / Model : Honda/ Shuttle hybrid

Colour : Black

Chassis No : GP71043538

Mileage : 114,636 km

Engine No : LEB4263435

CONDITION OF TYRES

	Make	Size	Thread Balance
Front Nearside	: Pirelli	185/60/ R15	80%
Front Offside	: Pirelli	185/60/ R15	80%
Rear Nearside	: Pirelli	185/60/ R15	80%
Rear Offside	: Pirelli	185/60/ R15	80%

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front ,right, left side and wheel rim.

(Details refer to the photographs attached)

Enclosed number of photographs: 77 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

Vehicle Registration No: SLJ 1362 D

Our Ref No: ATEC/08/0004/JM

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about **14 (Fourteen)** working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front bumper assy	Repair	\$ 1,800.00	\$ -
1	Front door assy RH	Warped	\$ 1,600.00	\$ 1,600.00
1	Front door assy LH	Repair	\$ 1,600.00	\$ -
1	Front door windscreen RH	Cracked	\$ 950.00	\$ 950.00
1	Front door inner panel RH	Warped	\$ 860.00	\$ 860.00
1	Front door weatherstripe RH	Warped	\$ 450.00	\$ 450.00
1	Front fender assy RH	Repair	\$ 1,500.00	\$ -
1	Front uniside RH	Repair	\$ 2,500.00	\$ -
1	Front door side mirror RH	Malfunction	\$ 980.00	\$ 980.00
1	Front door side mirror cover RH	Cracked	\$ 580.00	\$ 580.00
1	Front door window master switch RH	Malfunction	\$ 1,250.00	\$ 1,250.00
1	Front door lock w actuator RH	Malfunction	\$ 680.00	\$ 680.00
1	Front side skirt RH	Warped	\$ 700.00	\$ 700.00
1	Front wheel hub bearing LH	Bent	\$ 860.00	\$ 860.00
1	Front wheel shock absorber LH	Bent	\$ 830.00	\$ 830.00
1	Front wheel hub bearing RH	Bent	\$ 860.00	\$ 860.00
1	Front wheel shock absorber RH	Bent	\$ 830.00	\$ 830.00
Total			\$ 18,830.00	\$ 11,430.00
Less 20%			\$ 3,766.00	\$ 2,286.00
			\$ 15,064.00	\$ 9,144.00

SPECIAL NETT ITEMS

1	Front tyre LH	Cut	\$ 280.00	\$ 280.00
1	Front wheel sports rims LH	Dented/Scratched	\$ 950.00	\$ 950.00
1	Front wheel cap LH	Cracked	\$ 150.00	\$ 150.00
1	Front tyre RH	Cut	\$ 280.00	\$ 280.00
1	Front wheel sports rims RH	Dented/Scratched	\$ 950.00	\$ 950.00
1	Front wheel cap RH	Cracked	\$ 150.00	\$ 150.00
1	Front bumper clips(1 set)	Necessary	\$ 120.00	\$ 120.00
			\$ 2,880.00	\$ 2,880.00
Total parts			\$17,944.00	\$ 12,024.00

Vehicle Registration No: SLJ 1362 D

Our Ref No: ATEC/08/0004/JM

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

Total cost of parts c/f	\$ 17,944.00	\$ 12,024.00
-------------------------	--------------	--------------

LABOUR

1	To cut, weld, straighten affected areas and replace damaged parts.	\$ 6,000.00	\$ 5,800.00
2	To putty and spray painting the affected areas. Job Allowance.	\$ 4,500.00	\$ 4,200.00
3	To check front door window switch and wiring.	\$ 280.00	\$ 260.00
4	To apply anti rust proofing to the affected areas.	\$ 240.00	\$ 220.00
5	To remove and install front door side mirror assy.	\$ 280.00	\$ 260.00
6	To remove and install front fender assy.	\$ 280.00	\$ 260.00
7	To remove and install front door lock components.	\$ 280.00	\$ 260.00
8	To remove and install front damaged wheel components	\$ 560.00	\$ 540.00
9	To remove and install front door assy.	\$ 560.00	\$ 540.00
10	To remove and install front side skirt.	\$ 280.00	\$ 260.00
11	To remove and install front bumper assy.	\$ 280.00	\$ 260.00
12	To conduct wheel alignment	\$ 350.00	\$ 300.00
13	To check central door lock system	\$ 350.00	\$ 300.00

Grand Total:	\$ 32,184.00	\$ 25,484.00
---------------------	---------------------	---------------------

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 20,300**

Vehicle Registration No: SLJ 1362 D

Our Ref No: ATEC/08/0004/JM

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

J&M Consultancy Pte Ltd



Joel Liew Jian Xiang
Automotive Appraiser

