

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22010744/APA3Q2**Date:** 24/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700086735
<b>Claimant Vehicle No :</b>	SJM9222E	<b>Insured Vehicle No :</b>	SLU5988P
Date of Loss:	27/10/2022	Nature of Claim:	TP
		Claim No:	2743566694SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJM9222E</b>	Engine No:	L15A2330040
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB31029672
Reg. Date:	04/12/2008 (Man. Year: 2008)	Odometer:	164620 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,915.20	5,852.08	5,063.12	46.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	2,390.00	1,790.00	42.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,095.20</b>	<b>8,242.08</b>	<b>6,853.12</b>	<b>45.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,600.00</b>		
<b>(S\$)</b>	15,095.20	6,600.00	8,495.20	56.28
<b>+ GST 7.00/7.00% (S\$)</b>	1,056.66	462.00	594.66	56.28
<b>Nett Amount (S\$)</b>	<b>16,151.86</b>	<b>7,062.00</b>	<b>9,089.86</b>	<b>56.28</b>
<b>+ Loss of Use (8.0 x S\$50.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>7,464.00</b>		

**INSPECTION**

Date of Assignment:	02/11/2022		
Date Inspected:	02/11/2022	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	7.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP - LH & RH	Not Necessary	97.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	845.10 FL	*845.10 FL
3	2		*REAR BUMPER SIDE HOLDER - LH & RH	Damaged	77.00 FL	*77.00 FL
4	1		*REAR BUMPER TOW COVER	Deformed	35.20 FL	*35.20 FL
5	1		*REAR END PANEL	Distorted	645.10 FL	*645.10 FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	228.30 FL	*228.30 FL
7	1		*TAILGATE	Distorted	1,288.10 FL	*1,288.10 FL
8	1		*TAILGATE LOCK	Damaged	282.90 FL	*282.90 FL
9	1		*TAILGATE INNER HOLDER	Cracked	55.90 FL	*55.90 FL
10	1		*TAILGATE WEATHERSTRIPE	Cut	225.40 FL	*225.40 FL
11	1		*TAILGATE OUTER GARNISH	Deformed	287.30 FL	*287.30 FL
12	1		*TAILGATE INNER TRIM BOARD	Deformed	366.40 FL	*366.40 FL
13	1		*TAILGATE WIPER MOTOR	Not Necessary	385.40 FL	*- FL
14	1		*TAILGATE GLASS MOULDING	Necessary	158.40 FL	*158.40 FL
15	1		*HONDA LOGO	Necessary	55.40 FL	*55.40 FL
16	1		*FREED WORDING	Necessary	68.70 FL	*68.70 FL
17	1		*SPORTS WORDING	Necessary	50.40 FL	*50.40 FL
18	1		*RS EMBLEM	Necessary	65.90 FL	*65.90 FL
19	1		*VTEC EMBLEM	Necessary	64.20 FL	*64.20 FL
20	1		*TURBO EMBLEM	Necessary	55.10 FL	*55.10 FL
21	1		*TAILLAMP - LH & RH	N/S Cracked	760.40 FL	*380.20 FL
22	1		*FLOOR PANEL	Repair	1,450.90 FL	*- FL
23	1		*FLOOR PANEL TOP CARPET	Not Necessary	337.20 FL	*- FL
24	1		*REAR FENDER INNER TRIM BOARD - LH & RH	N/S Deformed	910.20 FL	*455.10 FL
25	1		*REAR EXHAUST PIPE	Not Necessary	662.50 FL	*- FL
26	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	38.50 FL	*- FL
27	1		*REAR EXHAUST PIPE GASKET	Not Necessary	34.60 FL	*- FL
28	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
29	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
30	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
31	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
32	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
34	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*TAILGATE SURROUND LINING (RED)	Necessary	250.00 FS	*150.00 FS
36	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
37	1		*TAILGATE STICKER (BLACK)	Necessary	150.00 FS	*80.00 FS
38	1		*TAILGATE TOP SPOILER	Not Necessary	1,500.00 FS	*- FS
39	1		*REAR CAMERA	Damaged	480.00 FS	*380.00 FS
40	1		*FLOOR PANEL SEALANT	Not Necessary	60.00 FS	*- FS
41	1		*FLOOR PANEL INSULATION PAD	Necessary	250.00 FS	*200.00 FS
42	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,821.50</b>	<b>6,990.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,906.30	1,138.02
<b>Total Parts (\$\$)</b>	<b>10,915.20</b>	<b>5,852.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCKING & PULL OUT REAR DOOR PORTION & RENEW ABOVE PARTS	New	1,600.00	1,000.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO SPRAY TUFF COAT	New	150.00	80.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE EXHAUST PIPE	New	150.00	0.00
10	TO PUTTY & SPRAY UP PAINT WORKS	New	1,500.00	900.00
<b>Gross Labour Cost (S\$)</b>			<b>4,180.00</b>	<b>2,390.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**