



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE			Ref: CC4/ASM22010747/Tpa3q2 Date: 30/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4845C	Veh. Inspected	SLG 1495U	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M04DIT	Excess (\$)	0.00	
Assign From		Assign Date	27/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI SWIFT	c.c	1372	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JSAFZC82300332936	Colour	GREY	
Odometer	78211 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	GT RADIAL	6 mm	
L/H Front Tyre	185/55 R16	GT RADIAL	6 mm	
R/H Rear Tyre	185/55 R16	GT RADIAL	6 mm	
L/H Rear Tyre	185/55 R16	GT RADIAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/10/2022	Inspection Date	28/10/2022	
Survey held at	HUI HUANG HONG BAO MOTORS 2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	