

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

HSBC Insurance

GST Ref. No: 20-0000274-Z

Vehicle No: SJQ 1898L

Invoice No: G23SINVP000863

Chasis No : W0LBE6EA4G8093260

Engine No: B1161386FBXX0830

Invoice Date: 14/4/2023

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

<u>No.</u>	<u>Qty.</u>	<u>Description</u>	<u>Price (SGD)</u>
<u>1</u>	1	RR BUMPER UPPER	1800.00
<u>2</u>	1	RR BUMPER CENTER RETAINER	160.00
<u>3</u>	1	RR BUMPER LOW BRACKET RH	86.00
<u>4</u>	1	RR BUMPER LOW BRACKET LH	86.00
<u>5</u>	1	RR BUMPER REINFORCEMENT	970.00
<u>6</u>	1	RR BUMPER LOW GARNISH	572.00
<u>7</u>	1	RR BUMPER REFLECTOR LH	144.00
<u>8</u>	1	RR EXHAUST SILENCER BOX	1545.00
<u>9</u>	1	RR EXHAUST SILENCER BOX BAFFLE	244.00
<u>10</u>	1	RR EXHAUST SILENCER BOX MOUNTING	269.00
<u>11</u>	1	RR EXHAUST PIPE CENTER	1062.00

Supplementary Items

<u>16</u>	2	RR EXHAUST PIPE CLAMP	370.00
-----------	---	-----------------------	--------

Total: 7308.00
Less 10%: 730.80
Parts Total : 6577.20

Labour

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	650.00
<u>2</u>	Carry out spray painting on accident affected area. (Rear Tailgate, Rear bumper, Rear end panel)	550.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00
<u>4</u>	Remove and refit reverse sensor (Labour)	50.00
<u>5</u>	To remove and replace exhaust pipe	80.00

Labour Total : 1360.00

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Rear number plate	40.00
2	Rear Bumper clip Set	50.00

Other Total : 90.00

Total : 8027.20
GST (8%) 642.18
Grand Total: 8669.38

Yours Faithfully,


Ronnie Tan
Service Advisor
Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.