

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2210-584-TG

DATE : 29-Oct-2022

VEHICLE REG. NO. : SCX9699M

VEHICLE MAKE : ELANTRA AD 1.6 GLS AT (AMS)

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Door RH	1	\$ 1,850.00	\$ 1,850.00
2	Front Door RH Hinge Top	1	\$ 75.00	\$ 75.00
3	Front Door RH Hinge Lwr	1	\$ 75.00	\$ 75.00
4	Front Door RH Checker	1	\$ 50.00	\$ 50.00
5	Front Door Black Sticker	1	\$ 40.00	\$ 40.00
6	Front Door Weatherstrip	1	\$ 120.00	\$ 120.00
7	Front Door Weatherstrip Outside	1	\$ 80.00	\$ 80.00
8	A-Pillar RH Garnish Triangle	1	\$ 60.00	\$ 60.00
9	Side Mirror Assy RH	1	\$ 750.00	\$ 750.00
10	Side Mirror Assy RH Base Cover 87660X	1	\$ 60.00	\$ 60.00
11	Front Fender RH	1	\$ 1,250.00	\$ 1,250.00
12	Front Fendershield RH	1	\$ 100.00	\$ 100.00
13	Front Fendershield Mudguard RH	1	\$ 50.00	\$ 50.00
14	Front Bumper	1	\$ 500.00	\$ 500.00
15	Front Bumper Retainer RH	1	\$ 45.00	\$ 45.00
16	Front Headlamp RH	1	\$ 1,200.00	\$ 1,200.00
Total Spare Parts				\$ 6,305.00
	<u>SPECIAL NETT</u>			
17	Front Fendershield Clips	10	\$ 3.00	\$ 30.00
18	Front Bumper Clips	10	\$ 3.00	\$ 30.00
19	Edge sealant for New Door	1	\$ 60.00	\$ 60.00
Total Special Nett				\$ 120.00
	<u>LABOUR</u>			
20	Remove, Refit, Replace and Repair Affected Area	1	\$ 1,000.00	\$ 1,000.00
21	Spray painting RH - Front Door, Front Fender, Front Bumper, Bonnet	1	\$ 1,000.00	\$ 1,000.00
22	Transfer Door Fittings and Glass to New Door	1	\$ 80.00	\$ 80.00
23	Run, Diagnose, Rectify and Reset Fault Codes	1	\$ 150.00	\$ 150.00
24	Wheel Alignment	1	\$ 70.00	\$ 70.00
25	Anti-Rust Coating	1	\$ 50.00	\$ 50.00
26	Check and Rectify Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,380.00
Amount Before Excess				\$ 8,805.00
Add GST @ 7%				616.35
Total Amount Payable				\$ 9,421.35

Estimate prepared by: KenGuan

This is an estimate based on our inspection and does not cover any additional parts/labour which may be required after work has started. New damaged parts may not be evident on first inspection and discovered after dismantling.