

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2210-584-TG

DATE : 29-Oct-2022

VEHICLE REG. NO. : SCX9699M

VEHICLE MAKE : ELANTRA AD 1.6 GLS AT (AMS)

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

**ESTIMATE REPAIR COST**

| NO.                  | DESCRIPTION                                                             | QUANTITY | UNIT COST   | TOTAL COST          |
|----------------------|-------------------------------------------------------------------------|----------|-------------|---------------------|
| <b>SPARE PARTS</b>   |                                                                         |          |             |                     |
| 1                    | Front Door RH / DD                                                      | 1        | \$ 1,850.00 | \$ 1,850.00 ✓       |
| 2                    | Front Door RH Hinge Top / DT                                            | 1        | \$ 75.00    | \$ 75.00 ✓          |
| 3                    | Front Door RH Hinge Lwr / DT                                            | 1        | \$ 75.00    | \$ 75.00 ✓          |
| 4                    | Front Door RH Checker X AD                                              | 1        | \$ 50.00    | \$ 50.00 ✓          |
| 5                    | Front Door Black Sticker / AR                                           | 1        | \$ 40.00    | \$ 40.00 ✓          |
| 6                    | Front Door Weatherstrip / TA                                            | 1        | \$ 120.00   | \$ 120.00 ✓         |
| 7                    | Front Door Weatherstrip Outside X AD                                    | 1        | \$ 80.00    | \$ 80.00 ✓          |
| 8                    | A-Pillar RH Garnish Triangle X AD                                       | 1        | \$ 60.00    | \$ 60.00 ✓          |
| 9                    | Side Mirror Assy RH / BR                                                | 1        | \$ 750.00   | \$ 750.00 ✓ 638     |
| 10                   | Side Mirror Assy RH Base Cover 87660X / BR                              | 1        | \$ 60.00    | \$ 60.00 ✓ 40       |
| 11                   | Front Fender RH / DD                                                    | 1        | \$ 1,250.00 | \$ 1,250.00 ✓       |
| 12                   | Front Fendershield RH / CRV                                             | 1        | \$ 100.00   | \$ 100.00 ✓         |
| 13                   | Front Fendershield Mudguard RH / CRV                                    | 1        | \$ 50.00    | \$ 50.00 ✓          |
| 14                   | Front Bumper X AD                                                       | 1        | \$ 500.00   | \$ 500.00 ✓         |
| 15                   | Front Bumper Retainer RH X AD                                           | 1        | \$ 45.00    | \$ 45.00 ✓ 4238     |
| 16                   | Front Headlamp RH X AD                                                  | 1        | \$ 1,200.00 | \$ 1,200.00 ✓ 20%   |
| Total Spare Parts    |                                                                         |          |             | \$ 6,305.00 3390.40 |
| <b>SPECIAL NETT</b>  |                                                                         |          |             |                     |
| 17                   | Front Fendershield Clips / AR                                           | 10       | \$ 3.00     | \$ 30.00 ✓ 20       |
| 18                   | Front Bumper Clips X AD                                                 | 10       | \$ 3.00     | \$ 30.00 ✓          |
| 19                   | Edge sealant for New Door / AR                                          | 1        | \$ 60.00    | \$ 60.00 ✓ 30       |
| Total Special Nett   |                                                                         |          |             | \$ 120.00 50        |
| <b>LABOUR</b>        |                                                                         |          |             |                     |
| 20                   | Remove, Refit, Replace and Repair Affected Area                         | 1        | \$ 1,000.00 | \$ 1,000.00 ✓ 400   |
| 21                   | Spray painting RH - Front Door, Front Fender, Front Bumper, Bonnet X AD | 1        | \$ 1,000.00 | \$ 1,000.00 ✓ 650   |
| 22                   | Transfer Door Fittings and Glass to New Door                            | 1        | \$ 80.00    | \$ 80.00 ✓ 50       |
| 23                   | Run, Diagnose, Rectify and Reset Fault Codes                            | 1        | \$ 150.00   | \$ 150.00 ✓ 100     |
| 24                   | Wheel Alignment                                                         | 1        | \$ 70.00    | \$ 70.00 ✓          |
| 25                   | Anti-Rust Coating                                                       | 1        | \$ 50.00    | \$ 50.00 ✓ 30       |
| 26                   | Check and Rectify Wiring                                                | 1        | \$ 30.00    | \$ 30.00 ✓          |
| Total Labour         |                                                                         |          |             | \$ 2,380.00 1330    |
| Amount Before Excess |                                                                         |          |             | \$ 8,805.00         |
| Add GST @ 7%         |                                                                         |          |             | \$ 616.35           |
| Total Amount Payable |                                                                         |          |             | \$ 9,421.35         |

Estimate prepared by: Ken Guan

This is an estimate based on our inspection and does not cover any additional parts/labour which may be required after work has started. New damaged parts may not be evident on first inspection and discovered after dismantling.

LKK Auto Consult  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

P/P-4770.40