

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Repair Shop

Shop Name:Automotive Repair Centre Pte Ltd

Address:

Zip Code:

Telephone:

Email:arc04kg@gmail.com

SN:985496013635

Test Time:2022-11-12 09:27:04

Technician Name:KG



Vehicle Information

License #:scx9699m

Year:2018

Make:Hyundai

Model:ELANTRA(AD)

VIN:KMHD841CMJU728733

Engine Size:G 2.0 MPI

Vehicle Software Version:V51.41

Diagnostic Application Version:V7.00.009

Diagnostic path:16 PIN DLC > Manually Select > General Area > Elantra(AD) > 2018 > G 1.6 MPI



System fault code

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-lock Braking System)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.Body Control Module
- 7.Cluster Module
- 8.Smart Junction Block
- 9.TPMS (Tire Pressure Monitoring System)
- 10.EPS (Electronic Power Steering)
- 11.Smart Key Unit

12.CODE (Transmitter Code Saving)