

SMX2562B

BMW 420i Gran Coupe.

WBA4D32070G382956

TP Chin

Xiao Tong

Front Bumper	Debond	1353	✓
Front Bumper Lips.	~	50(SN)	✓
Front Bumper Side Holder RH.	Drill	104	✓
Front Bumper Sponge.	XHP	175	X
Front Bumper Reinforcement	NEU	768	X
Front Bumper Sensor	XHP NEU	255	X
Front Bumper Fog Lamp RH	NEP NEU	312	X
Front Bumper Fog Lamp Cover RH	NEP ~	141	X
Front Bumper Lower Spoiler	anled	1800(SN)	1200(SN)
Front Bumper Nozzle Pump RH	XHP NEU	195	X
Front Bumper Nozzle Pump Cover RH.	Missing	53	✓
Front Bumper Logo.	NEU	85	✓

SMX2562B.

Headlamp RH Cracked 2163 ✓

Headlamp lower Bracket RH. ~~HE MR~~ 95. X.

Headlamp Module RH. Dmgd 368 ✓

Headlamp Ballast RH. ~~HE MR~~ 395. X

Bonnet Rep's 2551. X

Front RH Fender Rep's 868 X

Front RH Wheel Rim. At ~~1200~~ 850 (SN).

4126 S.N. 2100

3713.40

Smx 2562B.

Panel Beating

~~800~~ 400

Spray Painting

~~800~~ 250

Wiring

860

~~50~~ 30

To perform diagnostic test.

~~200~~ 100.

To perform wheel alignment.

~~150~~ 80.

total: 6~~6~~73.40

r/s: 5.3K.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: