

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHD4433S**
 MAKE **HYUNDAI**
 MODEL **IONIQ**

DATE: **25.10.22**
 MVA **JUMANI**
 DOA: **23.10.22**

CP(P)
CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MLDG			\$451.25
1	REAR BUMPER BEAM			\$394.80
10	REAR BUMPER CLIPS			\$22.00
SUB TOTAL				\$1,327.45
LESS 20%				\$265.49
DISCOUNTED TOTAL				\$1,061.96
	REAR NUMBER PLATE			\$50.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINT			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$50.00
	TOWING.			\$160.00
TOTAL LABOUR				\$750.00
ESTIMATE TOTAL				\$1,861.96

XR
 / DEF
 ? X SVC
 X SVC

NET / SCR

350
 250
 30
 ✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LICK
 25/10/2022 1800
 PIP
 2 Days
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

