

(06/11/22)

ASS. REC. BY:

HT

N92

REF:

CTI

CHANG. 4/5

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SH 97674

Yr Regn:

23

108/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS HYBRID

c.c

1798

Colour

BLUE

A/C:

Insured / Std / NI / NA

Sp. Reading

battery flat

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4303563489

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

WESTLAKE (CF), DUN (R)

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

20/10/2022

D.O.I.

25/10/2022

Survey held at

CDGE LOYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/11/2022 FINALIZED LUMP SUM REPAIR \$3,250.00 / 3 REPAIR DAYS

Date/Time, File Pass to?

Preli. Report

1)

Date/Time, File Return to?

Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp

(\$)

Interview

(\$)

Tech. Invs

(\$)

Weekend

(\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL