

REPAIR ESTIMATE*

17.10.2022

MODEL **HYU-140**

Type

CHIANG/ ~~AG~~

CHWTF

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER / CMA		\$553.00
1	REAR BUMPER LOWER COVER ?		\$228.00
1	REAR REINFORCEMENT ?		\$428.40
10	REAR BUMPER CLIPS / MBL	\$2.20	\$22.00
2	REAR BUMPER BRACKET LH/RH X 5 n n	\$35.60	\$71.20
1	REAR BUMPER REFLECTOR /LH X		\$32.00
	SUB TOTAL		\$1,334.60
	20.00%		\$266.92
	DISCOUNTED TOTAL		\$1,067.68
1	REAR BUMPER MAT / MBL		\$50.00
1	REAR REVERSE SENSOR / CMA		\$135.70
			\$185.70
	Labour Charge		
	Panel Beating		\$400.00
	Spray Painting Charge		\$300.00
	Remove/refix reverse sensor		\$60.00
	Check Lighting & Wiring		\$40.00
	TOTAL LABOUR		\$800.00
	ESTIMATE TOTAL		\$2,053.38
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

2 Days.
4/5
Gone off
18/10
3pm

KKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices to be given in written information
- Third parties to be notified "Without Prejudice" basis
- No litigation to be initiated against A&A
- Supply of materials to be provided and
is subject to approval by Insurance Company

Acknowledged: _____
Signature: _____
Date: _____