

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0934/2022/EQ
DATE : 27-Oct-22
WIP : 47860

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHIANG FOCK PONG
ADDRESS : BLK 921 JURONG WEST STREET 92
#07-65
SINGAPORE 640921
TELEPHONE : HP +65 96626826
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700086735-04
VEHICLE NO : **SLU 5988 P**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 7/12/2017
ENGINE NO : CHZ 594541
CHASSIS NO : WAUZZZGA6JA040009
MILEAGE : 109,603
DATE IN : 27-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Oct-22
PLACE OF ACCIDENT : PIE TOWARDS TUAS BEFORE STEVENS ROAD
EXIT, 1ST LANE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 5988 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	360 360 ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	400 400 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	1200 500 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	2000 1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	192 192 ✓
TOTAL LABOUR CHARGES		:	\$ 4,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5988 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,430.00	✓ 1654
2	FRONT BUMPER GRILLE - CENTER <i>Rehd</i>	1	\$ 220.00	✓ 175.60
3	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>RH ut</i>	2	\$ 378.00	✓ 176. 151.20
4	FRONT BUMPER END CAP - LH / RH <i>new</i>	2	\$ 132.00	✓
5	FRONT BUMPER SPOILER <i>Rehd</i>	1	\$ 332.00	✓ 265.60
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 174.00	✓
7	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 76.00	✓
8	FRONT BUMPER ADAPTER - LH / RH <i>? nn</i>	2	\$ 88.00	? x
9	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,561.00	✓ 1248.80
10	RADIATOR GRILLE STRIKER PLATE <i>? nn</i>	1	\$ 138.00	? x
11	FRONT BUMPER REINFORCEMENT BEAM <i>? dented</i>	1	\$ 769.00	? 614.80
12	FRONT BUMPER FOAM FILLER PIECE <i>? nn</i>	1	\$ 87.00	? x
13	FRONT BUMPER TOP COVER <i>Rehd</i>	1	\$ 112.00	✓ 89.60
14	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 80.00	+
15	FRONT BUMPER DISTANCE PIECE <i>? nn</i>	1	\$ 16.00	? x
16	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	✓ 12.40
17	AIR CONDITIONER STICKER	1	\$ 9.00	✓ 6.64
18	FRONT WHEEL HOUSING LINER - RH <i>new</i>	1	\$ 213.00	+
19	HORN HIGH TONE - RH <i>new</i>	1	\$ 181.00	+
20	HORN BRACKET - RH <i>new</i>	1	\$ 35.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,047.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5988 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HEADLIGHT MOUNTING	1	\$ 132.00	+
22	HEADLIGHT - RH	1	\$ 5,245.00	+
23	HEADLIGHT MOUNTING	1	\$ 132.00	+
24	LIFT CYLINDER - RH	1	\$ 156.00	+
25	LIFT CYLINDER HOSE	1	\$ 204.00	+
26	RADIATOR AIR GUIDE - RH torn	1	\$ 35.00	27.76
27	RADIATOR OUTER SEAL - RH	1	\$ 8.00	+
28	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 25.00	+
29	RADIATOR AIR GUIDE - LH	1	\$ 35.00	+
30	NOISE INSULATION	1	\$ 353.00	+
31	FRONT WHEEL COVER - LH / RH	2	\$ 720.00	576
32	FRONT NO PLATE	S/N	\$ 60.00	60
33	SUNDRIES		\$ 400.00	x
TOTAL SPARE PARTS		:	\$ 14,552.00	
TOTAL LABOUR CHARGES		:	\$ 4,152.00	
GRAND TOTAL		:	\$ 18,704.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Adrian
28/01/22

Not Authorised, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT