

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22010768/AGVY3M4**Date:** 15/03/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001962586
Claimant Vehicle No :	SJF470B	Insured Vehicle No :	SMX6799J
Date of Loss:	07/10/2022	Nature of Claim:	TP
		Claim No:	287130

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF470B		
Make & Model:	AUDI A4, 1.8 T FSI MU CVT ABS D/AIRBAG 2WD 4DR (A)	Engine No:	CAB007345
Reg. Date:	15/05/2008 (Man. Year: 2008)	Chassis No:	WAUZZZ8K18A021921
Colour:	Grey	Odometer:	170930 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,897.25	3,350.70	7,546.55	69.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,090.00	620.00	36.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,607.25	4,440.70	8,166.55	64.78
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	12,607.25	3,500.00	9,107.25	72.24

INSPECTION

Date of Assignment:	28/10/2022	
Date Inspected:	17/11/2022	Inspected At: Lc Automotive Blk 25 Kaki Bukit Rd 4, # 05-26 Synergy @ KB Singapore 417800
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts:	143	AUDI A4 1.8 T FSI MU CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF470B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-RH	Distorted	2,163.00 F	*2,163.00 FL
2	1		*REAR DOOR OUTER HANDLE -RH	Not Necessary	195.20 F	*- FL
3	1		*REAR DOOR TOP HINGES-RH	Not Necessary	211.00 F	*- FL
4	1		*REAR DOOR LOWER HINGES-RH	Not Necessary	211.00 F	*- FL
5	1		*REAR DOOR INNER LOCK -RH	Damaged	655.00 F	*350.00 FL
6	1		*REAR DOOR INNER TRIM BOARD-RH	Cracked	1,210.10 F	*985.00 FL
7	1		*REAR DOOR INNER GEAR-RH	Not Necessary	582.10 F	*- FL
8	1		*REAR DOOR INNER GEAR MOTOR-RH	Not Necessary	681.55 F	*- FL
9	1		*REAR DOOR INNER SPONGE - RH	Not Necessary	182.55 F	*- FL
10	1		*REAR DOOR INNER RUBBER-RH	Cut	225.00 F	*225.00 FL
11	1		*REAR DOOR TOP MOULDING - RH	Not Necessary	172.25 F	*- FL
12	1		*REAR DOOR SIDE SKIRT -RH	Not Necessary	865.30 F	*- FL
13	1		*REAR R/H LOWER ARM	Not Necessary	551.00 F	*- FL
14	1		*REAR R/H BEARING	Not Necessary	225.00 F	*- FL
15	1		*REAR TYRE -RH	Not Necessary	400.00 F	*- FL
16	1		*REAR R/H RIM	Not Necessary	600.00 F	*- FL
17	1		*REAR R/H FENDER	Repair	1,385.20 F	*- FL
18	1		*REAR FENDER COWLING R/H	Not Necessary	350.00 F	*- FL
19	8		*REAR FENDER COWLING CLIPS	Not Necessary	32.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	10,897.25	3,723.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	372.30
Total Parts (S\$)	10,897.25	3,350.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-FIX UNDERCARRIAGE	New	180.00	0.00
2	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	0.00
3	TO CHECK WIRING SYSTEM	New	60.00	30.00
4	TUFF KOTE	New	120.00	60.00
5	PANEL BEATING	New	600.00	500.00
6	SPRAY PAINTING	New	600.00	500.00
Gross Labour Cost (S\$)			1,710.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >