

LC AUTOMOTIVE

25 KAKI BUKIT ROAD 4 #05-26 Synergy @ KB Singapore 417800

FAIZ FAISAL
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

18th NOV 2022

TP M816, Veron.

WAU2228K18A

Accident date: 07th OCT 2022

Estimated repair cost for vehicle no: SJF470B AUDI A4

S/n	Qty	Items	U/price	Amount
1	1	Rear door-RH <i>Distorted.</i>		2163 ✓
2	1	Rear door outer handle -RH <i>free new</i>		\$195.20 x
3	1	Rear door top hinges-RH <i>free new</i>		\$211.00 x
4	1	Rear door lower hinges-RH <i>free new</i>		\$211.00 x
5	1	Rear door inner lock - RH <i>Damaged.</i>		\$655.00 450 350
6	1	Rear door inner trim board-RH <i>cracked.</i>		\$1,210.10 185.
7	1	Rear door inner gear-RH <i>free new</i>		\$582.10 x
8	1	Rear door inner gear motor-RH <i>free new</i>		\$681.55 x
9	1	Rear door inner sponge - RH <i>free new</i>		\$182.55 x
10	1	Rear door inner rubber-RH <i>free new</i>		\$225.00 ✓
11	1	Rear door top moulding - RH <i>free new</i>		\$172.25 x
12	1	rear door side skirt -RH <i>free new</i>		\$865.30 x
13	1	rear R/H lower arm <i>free new</i>		\$551.00 x
14	1	rear R/H bearing <i>free new</i>		\$225.00 x
15	1	Rear tyre -RH <i>free new</i>		\$400.00 x
16	1	rear R/H rim <i>free new</i>		\$600.00 x
17	1	Rear R/H fender <i>Repair</i>		\$1,385.20 x
18	1	Rear fender cowling R/H <i>free new</i>		\$350.00 x
19	8	rear fender cowling clips <i>free new</i>	\$4.00	\$32.00 x

Subtotal :- \$10,189.45

Labour charges

To remove & re-fix undercarriage \$180.00 x

To check wheel alignment computer \$150.00 x.

To Check Wiring System \$60.00 30.

Tuff Kote \$120.00 60.

Panel beating \$600.00 500.

Spray painting \$600.00 500.

Subtotal :- \$1,710.00

Total:- \$11,899.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 444070.

h/s: 3.5K.

05 Days.

3.5K